
cnt < 26 / next bit
reset
IDLE
busy_q = 0
start / load, cnt = 0
cnt == 26 / load rcp_q, done_q = 1
BUSY
busy_q = 1
start / reload (undefined use)