

Main Board Build Cheat Sheet

Component Values

C1: 10 μ F
C2: 100 μ F
C3: 10 μ F
C4:
C5: 100 nF
C6: 100 nF
C7: 22 pF
C8: 22 pF
C9: 100 nF
C10: 100 nF
C11:
C12:
C13:
C14: 100 nF
C15: 100 nF

R1: 10k Ω
R2: 10k Ω
R3: 10k Ω

Hookups

Encoder 0: Right wheel
Encoder 1: Left wheel
Encoder 2: Turret motor
Encoder 3: Turret calibration

Bump 0: Front bumper
Bump 1: Rear bumper

Pinout

[Regardless of the actual pin value on the board, these pins are numbered from left to right, when facing the header, looking toward the edge of the board.]

Programming Header:

1. Reset
2. Tx
3. Rx
4. 4.5V
5. No Connection
6. Gnd

Power Out:

1. 4.5 V
2. Gnd

SigOut:

1. IRRx
2. IRTx
3. SDA
4. SCL