AMAZON BASE BUILDING COMPLIANCE STANDARD

Task Title	Scaffold
APM Object	CT.HEIGHT.SCAFFOLD
APM Description	Scaffolding - any temporary structure used to support people or equipment for access to elevated work areas
General tasks always required	Follow safety procedures - e.g. 1MRA, LOTO, PPE, etc. Ensure that all WOs are carried out by qualified, certified staff with appropriate familiarisation and supervision as required Add notes for each observation and create a FWO if necessary to eliminate defects Use appropriate tools, chemicals and industry standard practices (RME policy permitting) Ensure relevant logs, readings and certification is uploaded to APM prior to WO closure. CT evidence must be additionally uploaded to the DMS (WorkDocs in DE) To suggest improvements please raise a SIM or contact document authors Leonardo Vitale (LEOVITAL) Rob Gisby (EWARTGXR) or APM, Benito Sanchez Sanchez de Puerta (BPPUERTA) SIM - Link to SIM template

Last Update: (Version)	ago-23	**Last Update Change Detail:**	Transfer to new template. Rationalisation of EU RME Minimum standards. Alignment with dependant PM. Released as Draft.	**Activities may be covered by No-Go restrictions:**	Not Specified	**Special Certification Required:**	**Delivered By:**
Evidenced part or full by PM:	Not Specified	**Related BBM PM:**	Not Specified	**Related CT Areas:**	Not Specified		

Scope

Any site where scaffolding is used to work at height.

Using this document

This document is intended as a guide and may not be exhaustive. Whilst this document is based extensively on professional guidance and subject to periodic review, individual sites must be diligent to ensure they are aware of, and comply to, local and changing regulations.
The format of these standards is intended to improve navigation between maintenance and compliance standards and to allow frequent, minor updates to a single living resource. Please avoid offline or printed versions and check version dates and change log.
In the event of becoming aware of errors or omissions in this document, sites must provide detail, including references to relevant source information to their local planner for escalation - SIM Link above.
This document is considered released as draft.
For Information contact Authors: R Gisby (ewartgxr), Leonardo Vitale (leovital) and Benito Sanchez Sanchez de Puerta (bppuerta)

Maintenance and Compliance Relationship

Where relevant, associated Base Building PM's are listed on the header . In many cases maintenance contributes to, or fulfils compliance requirement. This may not be exhaustive and is intended to assist users to identify relevant maintenance.
If a BBM Maintenance activity fully meets the compliance requirements below, periodic upload of PM evidence will be required to APM and DMS / Workdays depending on region.

Key to Abbreviations

The key to the below document is as follows:
CT - Amazon compliance / statutory task - not otherwise covered by a BBM Standard PM. Evidence to be provided into APM and DMS upon task closure.
CT* - This is a conditional task based or based on findings from previous inspections. If a frequency is not used, a further appropriate frequency needs to be in either the region, or 'ALL'. Local teams must ensure appropriate frequency.
(CT) - Compliance task which is likely met or exceeded by a CT task in [ALL] and therefore achieved by proxy BUT local site must satisfy themselves that requirements are fully met.
PM - Requirement can demonstrated through appropriate maintenance - Refer to relevant PM Standard
(PM) - Maintenance task which is met or exceeded by a PM task in [ALL] and therefore achieved by proxy BUT local site must satisfy themselves that requirements are fully met including regional / manufacturer requirements.
EVID - Periodic upload of evidence to DMS, for non-CT task lines. For example, evidence of PM completion, certification, licence etc.
EVID* - Conditional requirement to upload evidence at the interval provided
N A R - No Additional Requirement

Required Tasks

Region	Task Index	Task Frequency	Task Requirements	Qualification of Inspector	Records Required	PM	Weekly	Monthly	3 Monthly	6 Monthly	12 Monthly	24 Monthly	Additional
FR	3	No additional requirements	Inspection as per [2].	No additional requirements	Training records			CT					
IT	5	No additional requirements	Inspection as per [1] and [2].	No additional requirements	Manufacturer's mark			CT					
IT	6	When modifications, long period without use, seismic episode or when any condition that could affect the stability or resistance	Inspection as per [2].	Competent person with university or professional degree or with more than 2 years of experience in scaffolders.	No additional requirements			CT					
PL	2	Regular inspection every 10 days by relevant engineer. Ad-hoc reviews - after 2 weeks of scaffold being unused and after each thunder with wind speed exceeding 12 meters/sec	Additional inspections according to Polish norm PN-M-47900-2:1996	No additional requirements	The scaffolding acceptance should be confirmed with an entry in the construction logbook or in the technical acceptance protocol, Scaftag								CT
ROI	4	Regular inspections every week.	Inspection as per [2].	No additional requirements	Inspection records to be kept for 5 years. Maintenance logbook.		CT						

UK	1	Weekly inspection. Additionally, following any circumstance liable to jeopardise the safety of the installation (e.g adverse weather conditions, impact)	Inspection as per [2].	No additional requirements	Inspection report. Tag system is recommended to signal people that scaffold has been inspected		CT						

Related Regional Legislation			
Region	**Relevant legislation**	**Vendor Certification**	**Statutory requirement**
CZ	Regulation No. 101/2005 Coll. Regulation No. 378/2001 Coll.	Competent person, best practice to outsource to specialist company.	Inspections carried out every 12 months.
DE	Technische Regeln für Betriebssicherheit: TRBS 1201 - Prüfungen und Kontrollen von Arbeitsmitteln und überwachungsbedürftigen Anlagen TRBS 2121 Teil 1 - Gefährdungen von Personen durch Absturz - Bereitstellung und Benutzung von Gerüsten DGUV Information 201-011 - Handlungsanleitung für den Umgang mit Arbeits- und Schutzgerüsten	Qualified person for acceptance inspection (befähigte Person). Competent person for general inspection.	Acceptance inspection after setting up, modifications and before initial operation. Visual inspections before each use and based on risk assessment.
ES	UNE-EN 12810 Standard on Scaffolders UNE-EN 12811 Standard on Performance requirements and general design RD 2177/2004 for him that the minimum provisions are established safety and health for use by the workers of the work teams, in terms of temporary work at height. RD 1215/97 establishing minimum security provisions and Health for the use by workers of work equipment. Prevention Technical Note NTP 1015 Prevention Technical Notes NTP 1016	Competent person with university or professional degree or with more than 2 years of experience in scaffolders.	Inspections at start of each day and after exceptional weather. Recommended to inspect the area before the installation
FR	Art 6 Decree of 21 December 2004 "Arrêté du 21 décembre 2004 relatif aux vérifications des échafaudages et modifiant l'annexe de l'arrêté du 22 décembre 2000 relatif aux conditions et modalités d'agrément des organismes pour la vérification de conformité des équipements de travail" Arrêté du 21 décembre 2004 relatif aux vérifications des échafaudages et modifiant l'annexe de l'arrêté du 22 décembre 2000 relatif aux conditions et modalités d'agrément des organismes pour la vérification de conformité des équipements de travail - Légifrance (legifrance.gouv.fr)	Qualified person.	Inspections carried out initially, daily and quarterly.
IT	Legislative Decree 9.04.2008 n° 81 art. 122 UNI EN 12810:2004 (Specifications) UNI EN 12811:2004 (Performance requirements) UNI EN 74:2007 (Joints) UNI EN 16508:2016 (Coverage and encapsulation) UNI EN 13374:2019 (Temporary lateral protection)	Competent and trained person.	Depends on type of scaffold. Verification before and after assembly. Inspections at regular interval and after exceptional weather conditions or temporary interruption of work.
PL	Regulation of the Minister of Infrastructure of 6 February 2003 on occupational health and safety during construction works.	Competent person.	Acceptance inspection after placing the scaffolding. Periodically inspection, at least once a month (10 days after bad weather conditions)
ROI	S.I. No. 299/2007 - Safety, Health and Welfare at Work (General Application) Regulations 2007 (irishstatutebook.ie)	Competent person, best practice to outsource to specialist company.	Inspection once erected and at least every week. Maintenance programme in place.
SK	Ordinance No. 147/2013 Coll., laying down details for ensuring safety and health protection in construction work and work related to them and details on professional competence to perform certain work activities Government Regulation no. 392/2006 Coll. on the minimum safety and health requirements for the use of work equipment Government Regulation no. 396/2006 Coll. on the minimum safety and health requirements for the construction site STN 73 8101/a: Scaffolding. Common provisions.	Competent person, best practice to outsource to specialist company.	Scaffolding must be inspected before its first use. Regular interval: Every 30 days for fixed scaffolding, every 14 days for mobile scaffolding, or exposed to the effects of mechanical vibration and always after temporary interruption of work or exceptional weather conditions.
UK	The Workplace (Health, Safety and Welfare) Regulations 1992 (legislation.gov.uk) The Work at Height Regulations 2005 (legislation.gov.uk) The Provision and Use of Work Equipment Regulations 1998 (legislation.gov.uk) Health and Safety at Work etc. Act 1974 (legislation.gov.uk) Provision and Use of Work Equipment Regulations (Northern Ireland) 1999 (legislation.gov.uk) The Work at Height Regulations (Northern Ireland) 2005 (legislation.gov.uk)	Competent person, best practice to outsource (scaffolder).	Inspection once erected and at least every week. Bad weather conditions might require more frequent inspections.