



- All holes are threaded for M2.5x0.45 screw
- Tolerance follow ISO 2768 standards
- NO retaining sharp corners required



