

TCF1 & TCF2 VIN Generation PPC Dashboard

Painted Body Storage (PBS) Buffer Allocation & Multi-Stage Material Availability Summary

System Online

Interface Theme

White Theme

> Control Panel: File Uploads & Engine Starting Stocks (Click to Expand/Collapse)

Update Dashboard Data

Report is generated. Uploading new files or updating engine clearances will pause auto-runs until you click 'Update Dashboard Data'.

Summary Report & Excel Download Cockpit & Wiring Shortage Reports TCF 1 Line (Altroz/Punch/Nova) TCF 2 Line (Harrier/Safari) Total Float Details & Search Quality Hold Registry Telegram Dispatcher

Cockpit & Wiring Shortage Reports

Real-time shortage monitoring for Cockpit Assemblies and Front Wiring Harnesses matching engine summary models across TCF1 and TCF2 lines.

COCKPIT SHORTAGES

30 Parts

Critical Shortage

WIRING SHORTAGES

10 Parts

Critical Shortage

MONITORED COCKPITS

126 Part Numbers

MONITORED WIRING

59 Part Numbers

ALERT: TODAY VIN GENERATION EXCEEDS CLEARANCE AFTER 6:30 AM (13 Items)

The following parts / aggregates have Today VIN quantity exceeding the 6:30 AM Clearance quantity:

Category	Model / Part Description	Clearance After 6:30AM	Today VIN	Excess VIN Qty
Cockpit	547354600105 (Harrier EV)	14	38	+24
Cockpit	547354600194 (Harrier EV)	3	14	+11
Cockpit	547354600114 (Harrier EV)	0	7	+7
Cockpit	547954600130 (Harrier / Safari Petrol TGDI MT)	0	4	+4
Cockpit	547954600107 (Harrier / Safari Petrol TGDI AT)	3	4	+1
Cockpit	549054600108 (Harrier / Safari Diesel AT)	4	6	+2
Cockpit	549054600117 (Harrier / Safari Diesel AT)	0	4	+4
Cockpit	548654600107 (Harrier / Safari Diesel MT)	10	12	+2
Cockpit	548654600108 (Harrier / Safari Diesel AT)	5	7	+2
Cockpit	549054600182 (Harrier / Safari Diesel AT)	1	2	+1
Cockpit	548654600206 (Harrier / Safari Diesel AT)	0	1	+1
Wiring	547354600173 (Harrier EV)	37	38	+1
Wiring	546854620387 (Punch EV (Nova))	28	33	+5

Display Filter:

Critical Shortages Only All Parts & Current Stock

Filter by TCF Line:

All Lines (TCF1 + TCF2)

Search Part / Model:

Search part number or model...

Cockpit Shortage Report

Cockpit Part Number	Model	LINE	Clearance After 6:30AM	Today VIN	Paint TOTAL FLOAT	PBS FLOAT	Cabs Float UPTO SEALANT	Shortage PBS FLOAT	Shortage Upto Sealant	Shortage TOTAL FLOAT
549754600126	Punch MCE CNG MT	TCF1	27	19	11	0	4	8	4	-3
549754600109	Punch MCE MT	TCF1	33	23	24	2	6	8	4	-14
549754600127	Punch MCE CNG MT	TCF1	48	25	36	1	4	22	19	-13
549754600111	Punch MCE MT, Punch MT SA	TCF1	73	39	48	1	18	33	16	-14
549754600112	Punch MCE AMT	TCF1	40	28	30	2	5	10	7	-18
549754610188	Punch MCE CNG AMT	TCF1	17	7	17	0	9	10	1	-7
547354600105	Harrier EV	TCF2	14	38	30	0	28	-24	-52	-54
547354600194	Harrier EV	TCF2	3	14	9	0	7	-11	-18	-20
547354600114	Harrier EV	TCF2	0	7	5	0	3	-7	-10	-12
547854600107	Harrier / Safari Petrol TGDI AT	TCF2	5	0	8	0	1	5	4	-3
547954600130	Harrier / Safari Petrol TGDI MT	TCF2	0	4	5	0	0	-4	-4	-9
547954600107	Harrier / Safari Petrol TGDI AT	TCF2	3	4	0	0	0	-1	-1	-1
547954600127	Harrier / Safari Petrol TGDI MT	TCF2	3	0	6	0	1	3	2	-3
547954600131	Harrier / Safari Petrol TGDI MT	TCF2	0	0	2	0	0	0	0	-2
549054600108	Harrier / Safari Diesel AT	TCF2	4	6	5	0	4	-2	-6	-7
549054600113	Harrier / Safari Diesel MT	TCF2	2	2	2	0	0	0	0	-2

549054600117	Harrier / Safari Diesel AT	TCF2	0	4	10	3	8	-7	-12	-14
549054600111	Harrier / Safari Diesel MT	TCF2	12	6	7	5	6	1	0	-1
548654600107	Harrier / Safari Diesel MT	TCF2	10	12	1	0	1	-2	-3	-3
548654600108	Harrier / Safari Diesel AT	TCF2	5	7	3	0	2	-2	-4	-5
548654600118	Harrier / Safari Diesel AT	TCF2	2	1	4	2	4	-1	-3	-3
548654600117	Harrier / Safari Diesel AT	TCF2	1	1	4	1	4	-1	-4	-4
548654600109	Harrier / Safari Diesel MT	TCF2	16	11	9	1	6	4	-1	-4
546854650115	Punch EV (Nova)	TCF1	48	23	39	0	15	25	10	-14
549054600182	Harrier / Safari Diesel AT	TCF2	1	2	2	1	2	-2	-3	-3
548654600206	Harrier / Safari Diesel AT	TCF2	0	1	1	0	0	-1	-1	-2
547854600207	Harrier / Safari Petrol TGDI MT	TCF2	0	0	1	0	1	0	-1	-1
549054600216	Harrier / Safari Diesel AT	TCF2	2	0	3	0	2	2	0	-1
548654600234	Harrier / Safari Diesel AT	TCF2	10	7	12	0	12	3	-9	-9
548654600233	Harrier / Safari Diesel AT	TCF2	2	0	7	0	5	2	-3	-5



⚡ Wiring Harness Shortage Report

Wiring Part Number	Model	LINE	Clearance After 6:30AM	Today VIN	Paint TOTAL FLOAT	PBS FLOAT	Cabs Float UPTO SEALANT	Shortage PBS FLOAT	Shortage Upto Sealant	Shortage TOTAL FLOAT
549754600138	Punch MCE CNG MT	TCF1	88	58	36	0	12	30	18	-6
549754600134	Punch MCE AMT	TCF1	50	28	30	2	5	20	17	-8
547354600173	Harrier EV	TCF2	37	38	30	0	28	-1	-29	-31
547354600104	Harrier EV	TCF2	22	14	9	0	7	8	1	-1
547854600174	Harrier / Safari Petrol TGDI MT	TCF2	6	1	6	0	1	5	4	-1
548654600142	Harrier / Safari Diesel AT	TCF2	15	13	8	0	6	2	-4	-6
548654600313	Harrier / Safari Diesel AT	TCF2	15	5	14	5	12	5	-2	-4
546854620387	Punch EV (Nova)	TCF1	28	33	16	2	10	-7	-15	-21
546854620346	Punch EV (Nova)	TCF1	49	23	39	0	15	26	11	-13
549054600257	Harrier / Safari Diesel AT	TCF2	17	10	26	1	21	6	-14	-19

Download Cockpit & Wiring Report (All Parts - 2 Sheets)

Download Critical Shortages Only (Excel)

