

TCF1& TCF2 VIN Generation PPC Dashboard

Painted Body Storage (PBS) Buffer Allocation & Multi-Stage Material Availability Summary

System Online

Interface Theme

White Theme

Control Panel: File Uploads & Engine Starting Stocks (Click to Expand/Collapse)

Data Sync & Upload

Auto-Sync Manual Upload

Sync directly from your OneDrive/SharePoint Macro Dashboard file.

OneDrive/SharePoint URL or Local File Path

https://tatamotors-my.sharepoint.com/:x/p/ngw11000658/IQA-56-OYPWAS7qTVfKIUu9RABUUH1BxPrEz_wi00kQzsns

Sync Now

Enable 5-Min Auto-Sync

Loaded Files Status

Download Updated BOM (.xlsx)

- FLOAT REPORT: Uploaded (19-08-2026 01:33 PM)
- FLOAT PAINT SUMMARY: Uploaded (19-08-2026 01:33 PM)
- SHOP WISE REPORT: Uploaded (19-08-2026 01:33 PM)
- Hourly Production Report: Uploaded (19-08-2026 01:33 PM)
- DPT TCF1 VIN Generation: Uploaded (19-08-2026 01:33 PM)
- DPT TCF2 VIN Generation: Uploaded (19-08-2026 01:33 PM)
- TCF1 ALTROZ COCKPIT STOCK: Uploaded (19-08-2026 03:21 AM)
- TCF1 NOVA COCKPIT STOCK: Uploaded (19-08-2026 03:21 AM)
- TCF2 COCKPIT STOCK: Uploaded (19-08-2026 03:21 AM)
- TCF1 WIRING STOCK: Uploaded (19-08-2026 02:39 AM)
- TCF2 WIRING STOCK: Uploaded (19-08-2026 12:39 AM)

Punch EV (Nova) Component Starting Stocks

Enter clearance counts for 5 critical Punch EV materials (Defaults: 0)

Battery	Combo	Tube Frame(Craddle)	Subframe	RTB
238 - +	198 - +	206 - +	220 - +	220 - +

Save Punch EV Clearances

Model Wise Shortage

Configure shortages by model, trim, part name, and clearance quantity.

Select Model Select Trim(s)
HARRIER / SAFARI Select trim(s)... (leave empty for All Trims)

Part Name Clearance Qty
Enter part name manually... 0 - +

Add Shortage Item

ICE Engine Starting Stocks

Enter clearance counts for ICE engines (Defaults: 0)

TCF1 Engines (Punch ICE)

Punch MT SA	Punch AMT SA	Punch TC MCE	Punch MCE MT
40 - +	2 - +	2 - +	500 - +

Punch MCE AMT	Punch MCE CNG MT	Punch MCE CNG AMT
163 - +	529 - +	149 - +

TCF2 Engines (Harrier / Safari ICE)

Harrier / Safari Diesel AT	Harrier / Safari Diesel MT	Harrier / Safari TGDI MT	Harrier / Safari TGDI AT
140 - +	112 - +	32 - +	57 - +

Save Engine Starting Stocks

Shift Start Stock Reset

Resets all starting clearance quantities to 0 and clears daily uploaded report cache.

Manual Trigger

Reset Clearances to 0 (Shift Start)

Update Dashboard Data

Report is generated. Uploading new files or updating engine clearances will pause auto-runs until you click 'Update Dashboard Data'.

Summary Report & Excel Download Cockpit & Wiring Shortage Reports TCF 1 Line (Altroz/Punch/Nova) TCF 2 Line (Harrier/Safari) Total Float Details & Search Quality Hold Registry Telegram Dispatcher

Shop-Wise Plant Production Summary (Daily Report)

Report Date: 14/8

Last Generated: 19-Aug-2026 08:42 AM

TCF1 VIN COUNT
574 cabs

TCF2 VIN COUNT
181 cabs

TOTAL TCF DROPPING
747 cabs

PAINT LIFTING
743 cabs

T60 COUNT
54 cabs

T40 COUNT
39 cabs

🚗 Model-Wise Production Matrix (TCF1 & TCF2 Breakdown)

MODEL		VIN	DROP	PAINT LIFTING	T60	T40
TCF1	PUNCH	440	437	438	40	0
TCF1	PUNCH Exports	11	18	9	0	0
TCF1	PUNCH EV	123	119	124	14	0
TOTAL TCF1		574	574	571	54	0
TCF2	HARRIER EV	82	84	76	0	18
TCF2	SAFARI	64	58	64	0	18
TCF2	HARRIER	28	31	32	0	3
TOTAL TCF2		174	173	172	0	39
GRAND TOTAL PLANT		748	747	743	54	39

📄 Export Model-Wise Production Matrix to Excel


🕒 Hourly Production & Line Generation Tracker

Live hour-by-hour tracking of VIN Generation and TCF Dropping across TCF1 and TCF2 assembly lines (Format: Hourly Output [Shift Cumulative Output]).

TCF1 DAY VIN 574 cabs ↑ A: 294 B: 280	TCF2 DAY VIN 174 cabs ↑ A: 75 B: 99	PLANT VIN TOTAL 748 cabs ↑ TCF1 + TCF2	TCF1 DAY DROP 574 cabs ↑ A: 303 B: 271	TCF2 DAY DROP 173 cabs ↑ A: 77 B: 96	PLANT DROP TOTAL 747 cabs ↑ TCF1 + TCF2
--	--	---	---	---	--

STAGE / LINE	03-04 PM	04-05 PM	05-06 PM	06-07 PM	07-08 PM	08-09:30 PM	09:30-10:30 PM	10:30-11:30 PM	SHIFT A TOTAL	SHIFT B TOTAL	SHIFT C TOTAL	DAY TOTAL PLANT
TCF1 VIN Gen	33 [33]	24 [57]	40 [97]	22 [119]	41 [160]	52 [212]	33 [245]	35 [280]	294	280	0	574
TCF2 VIN Gen	13 [13]	16 [29]	5 [34]	11 [45]	19 [64]	10 [74]	16 [90]	9 [99]	75	99	0	174
TOTAL VIN	46 [46]	40 [86]	45 [131]	33 [164]	60 [224]	62 [286]	49 [335]	44 [379]	369	379	0	748
TCF1 Drop	34 [34]	30 [64]	23 [87]	34 [121]	40 [161]	44 [205]	37 [242]	29 [271]	303	271	0	574
TCF2 Drop	10 [10]	13 [23]	10 [33]	13 [46]	12 [58]	14 [72]	12 [84]	12 [96]	77	96	0	173
TOTAL DROP	44 [44]	43 [87]	33 [120]	47 [167]	52 [219]	58 [277]	49 [326]	41 [367]	380	367	0	747

📊 View Hourly Dropping Line Charts (TCF1 & TCF2 Separate Lines)



📄 Export Hourly Production Tracker to Excel

🏗️ Paint Shop Float Summary

This report displays the paint shop buffer status by stage and model, matching the exact layout of the paint shop tracker sheet.

Paint Float	MODEL	TOTAL FLOAT	PBS FLOAT	PBS TO POLISHING	POLISHING TO TOPCOAT	TOPCOAT TO WETSANDING G ROOFBLACK	TOPCOAT TO WETSANDING G FRESH	WETSANDING G TO SEALANT	TOTAL UPTO SEALANT	PT ENTRY TO SEALANT	BIW LIFTING G TO PT	PT BYPASS	Today VIN
TCF1	PUNCH	512	23	25	30	6	25	54	163	80	269	0	450
TCF1	PUNCH.EV	208	7	15	20	12	2	57	113	31	64	0	123
TCF1	TCF1 TOTAL	720	30	40	50	18	27	111	276	111	333	0	573
TCF2	HARRIER.EV	127	1	18	5	4	9	34	71	17	39	0	82
TCF2	SAFARI	70	7	11	8	0	5	14	45	11	14	0	64
TCF2	HARRIER	62	9	10	7	2	3	8	39	13	10	0	28
TCF2	SAFARI.EV	3	0	1	0	0	0	1	2	0	1	0	0

TCF2	TCF2 TOTAL	262	17	40	20	6	17	57	157	41	64	0	174
	GRAND TOTAL	982	47	80	70	24	44	168	433	152	397	0	747

Engine & Battery Requirement Summary

This report summarizes raw engine inventory status against paint shop float and computes clear-to-build requirements.

Engine / Battery Part No	Model	TA Code	Clearance After 6:30AM	Today VIN	Bal	Paint Float			Engine & Battery requirement		
						PBS FLOAT	Float UPTO SEALANT	TOTAL FLOAT	With respect to PBS FLOAT	With respect to Sealant FLOAT	With respect to Total FL
54850000PTP001	Punch MT SA	3302	40	11	29	1	9	34	28	20	-5
54850000PTP002	Punch AMT SA	3404	2	0	2	0	0	0	2	2	2
54970000PTP002	Punch TC MCE	7349	2	0	2	0	0	0	2	2	2
54970000PTP003	Punch MCE MT	3641	500	151	349	9	55	172	340	294	177
54970000PTP004	Punch MCE AMT	3406	163	59	104	2	18	72	102	86	32
54970000PTP005	Punch MCE CNG MT	3627	529	166	363	5	53	183	358	310	180
54970000PTP031	Punch MCE CNG AMT	3403	149	63	86	3	23	49	83	63	37
	1.2 Lit Total			450		20	158	510			
546816111212	Nova	5468	198	123	75	7	112	208	68	-37	-133
	TCF1			573		27	270	718			
572900000118	Harrier / Safari Diesel AT	—	140	43	97	8	52	66	89	45	31
572900000120	Harrier / Safari Diesel MT	—	112	38	74	7	19	26	67	55	48
54780000PTP001	Harrier / Safari Petrol TGDl MT	—	32	5	27	1	8	20	26	19	7
54780000PTP002	Harrier / Safari Petrol TGDl AT	—	57	6	51	0	3	20	51	48	31
	2 Lit Total			92		16	82	132			
547380400103	Harrier EV	5473	160	82	78	1	69	127	77	9	-49
	TCF2			174		17	151	259			

Export Master Summary Reports to Excel

BOM not available for 6 Short Vehicle Code(s) (11 cab(s) affected). These cabs may be miscounted as Ready-to-TCF with blank/NaN parts until BOM is entered below.

Fix Missing/Incomplete BOM — 6 Short VC(s)

Short VC	Status	Missing Parts	Cab Count	Sample Product	Sample VIN
54977024A	Incomplete	Cockpit	5	HORNBILL	MAT634196TPRC8930
54831927A	Missing	Engine/Battery, Cockpit, Front Wiring	2	TAYRONA	MAT901005TWG32263
54781827A	Incomplete	Cockpit, Front Wiring	1	Q5	MAT871046TWH34520
54830727A	Missing	Engine/Battery, Cockpit, Front Wiring	1	TAYRONA	MAT901002TWH34493
54977424A	Missing	Engine/Battery, Cockpit, Front Wiring	1	HORNBILL	MAT634214TPHC6394
54977324A	Missing	Engine/Battery, Cockpit, Front Wiring	1	HORNBILL	MAT634213TPHC6395

+ Enter BOM for a Short VC

Short Vehicle Code

54977024A

Engine / Battery Part No.

Cockpit Part No.

Front Wiring Part No.

Save BOM Entry