Building Vision Task Force

August 13, 2013 at 6:30 p.m.

Team

- Karen Kamphuis
- Dale Veldheer (absent)
- Larry Van Rhee
- Mike DenBlyker (absent)
- Denny Drooger
- · Kelly Vandenbosh
- Scott Blackmer
- · Alison Major
- Ross Becksfort

Agenda

- Discuss the BVTF report from 2012. This report is in your folder and can be viewed on line at northholland.org/BVTF
- 2. Team Goal:

With information provided and reported to NHRC's consistory by the BVTF, this team will review and present brick-and-mortar options to consistory that would address those needs while keeping the vision of intentionally sharing the love of Jesus through compassion-filled hospitality.

Why, What, Who, How, When

There is a sample of what this looks like in the BVTF report.

1. Start answering questions from Methodology / Rationale

Next Steps

1. Next Steps

- How would the flow go, what would an update to the building look like, where would the storage go, etc...
- Homework: everyone draw a picture of the church the way they see it working
- Software to help play with? Google sketch up, omnigraffle, etc...?
- All need to collectively work towards STAYING OFF BUNNY TRAILS... Hold each other accountable to realistic goals.

2. Next Meeting:

• Tuesday, September 10, 6:30pm

Methodology / Rationale

Why:

Identified current and future need presented by BVTF as well as inquiries from various church members regarding future facility needs.

What:

Consistory has asked a team to review the report presented by the BVTF and put a recommendation together that would address those needs as well as consider future growth needs of NHRC. The report will address the needs identified in the BVTF report. The report will also include additions to the building and layout of the new facility on the existing property.

- Consider current building updates, roof, boilers and etc.
 - Replace current boilers within next 3 months (already in progress?)
 - BOILER REPLACEMENT CAN START NOW*
 - Location of electrical boxes and utilities
 - Lighting in sanctuary is poor. Could be addressed in next year.
 - Would interior updates be part of updating building?
- Fellowship Hall (p16)
 - Gymnasium / Multipurpose Room
- Kitchen (p16)
 - New appliances (especially stove, more freezers)
 - Is it a long term use? Or just 5 yrs or 10 yrs? Depends on next generation.
 - "Don't build it and expect them to come. Build it with a PLAN."
- Exterior (p17)
 - Entry for car port at Sanctuary level
 - Grade for accessibility for downstairs and upstairs
 - Fast and big elevators
 - Handicap Parking (number and location)
 - Wheelchair accessibility from parking lot and within church
 - Entry door confusion
 - Confusion on flow once in the church (where's the nursery?)
 - Indoor Storage Custodial
 - Outdoor Storage building and grounds
 - Memorial Garden options? Cremation memorial wall or in ground?
 - Parking Lot (near end of list, but still need to maintain it)
- Centralized offices Staff

- Classrooms Storage (p18)
 - Classroom size
 - Technology in the classrooms (only 2 TVs on carts)
 - Education storage
- Sanctuary
 - Size (can seat about 400 people, average number was 236, high at 277)
 - What fullness level makes it uncomfortable for visitors? 80%?
 - Maybe new sanctuary added on at ground level?
 - Repurpose current sanctuary space?
- Roofline
 - Would that need to be adjusted? Leave it for an architect.
 - NO FLAT ROOFS.
- Technology
 - · Classrooms need server? No.
 - · Church management system is on the cloud.
 - · Video feed of service for nursery or cry room.
 - · Video would need lighting and wiring, but that's all.
 - · Sound system can move to any part of building very easily.
 - Only sound issue would come up if we changed design of sanctuary.

Who:

8–10 individuals with knowledge of the church facility to assist with current needs of the church as well as those that can think forward about the future needs of the church and community.

How:

The team will work together on a macro level to accomplish this goal as well as use subcommittees that can focus on specific tasks.

When:

Not defined.