

# Ahsanullah University of Science and Technology (AUST) Department of Computer Science and Engineering

## **LAB REPORT**

Course No : CSE3108

Course Title : Microprocessors Sessional

Assignment No : 04

Date of Submission : 22-01-2021

Submitted To : Ms. Tahsin Aziz & Ms. Tanjila Broti

#### Submitted By:

Group : B1

Name : Anik Hassan Nibir

ID : 190104054

Section : B

9. Draw the given shape in dot matrix display and show the initials of the shape in seven segment display and glow the four LEDs according to the initials.

Half Frame

H

H

F

### Answen.

SSEG SEGMENT STACK 'STACK'

DW 100 Dup(?)

SSEG ENDS

DSEG SEGMENT 'DATA'

COUNT DB 5

DSEG ENDS

CSEG SEGMENT 'CODE'

MAIN PROC FAR

push Ds

MOV AX, O

push AX

MOV AX, DSEG

MOV DS, AX

MOV ES, AX

#### PRINT:

MOV DX, 2004H

MOV AL, 000000016

OUT DX, AL

MOV DX, 2030H

MOV AL, 010000006

OUT DX, AL

MOV CX, 0010H

L1: L009 L1

MOV DX, 2003H

MOV AL, 000000016

OUT DX, AL

MOV DX, 2030H

MOV AL, 001100006

OUT DX, AL

MOV CX, 0010H

L2: L00P 12

MOV DX, 2002H

MOV AL, 000000016

CUT DX, AL

MOV DX, 2030H

MOV AL, 01100006

CUT DX, AL

MOV CX, 0010H

L3: L00P L3

MOV DX, 2001 H

MOV AL, 000000016

OUT DX, AL

MOV DX, 2030 H

MOV AL, 011100106

OUT DX, AL

MOV EX, 0010 H

Ly: Loop L9

MOV DX, 2000H

MOV AL, 000000016

OUT DX, AL

MOV DX, 2030H

MOV AL, 01101106; H

OUT DX, AL

MOV DX, 2070H

MOV AL, 000000106

OUT PX, AL

MOV CX, 0050H

L5: LOOP L5

MOV DX, 2000H

MOV AL, 000000116

OUT DX, AL

MOV DX, 2031H

MOV AL, 001000006

OUT DX, AL

MOV CX, 0010H

L6: LOOP L6

Mov DX, 2000H

MOV AL, 000001116

OUT DX, AL

MOV DX, 2031H

MOV AL OOH OOOD

OUT DX, AL

MOV CX, boild H

L7: LOOP 17

MOV DX, 2000H

MOV AL, 000011116

out DX, AL

MOV DX, 2031H

MOV AL, 001100016

out DX, AL

MOV ex, 00/04

LS: LOOP LS

MOV DX, 2000H

Mov AL, ocollillb

out DX, AL

MOV DX, 2031H

MOV AL, 011100016

out DX, AL

MOV DX, 2070H

MOV AL, 000000116

OUT PX, AL

MOV CX, 0050H

19: LOOP L9

Mov Dx, 200017

MOV AL, OOIIIIIIb

out px, AL

MOV CX, ODIOH

L10 : LOOP L10

MOV DX, 2006H

Mov AL, OIIIIIIIb

OUT DX, AL

MOV CX, DOIDH

L11: LOOP L11

MOV DX, 2001H

Mov AL, volocool b

OUT DX, AL

MOV CX, DOIOH

L12: LOOP L12

MOV DX, 2002 H

Mov AL, 000100016

out DX, AL

MON GX ODIOH

L13: Loop L13

MOV DX, 2003H

MOV AL, 000010016

out DX, AL

Mov ex, odloH

L14: LOOP L14

MOV DX, 2003 H

Mov AL, 000011016

out DX, AL

MOV CX, DOIOH

L15; LOOP L15

MOV DX, 2004 H

MOV AL, 000001016

OUT DX, AL

MOV CX, 0060 H

L16: LOOP L16

MOV DX, 2004H

MOV AL, 000001006

OUT DX, AL

MOV PX, 2030H

MOV AL, OIIIODIOD

OUT DX, AL

Mov ex, ooloH

LO1; LOOP LO1

Mov Dx, 2003H

MOV AL, 000011006

OUT DY, AL

MOV DX, 2030H

MOV AL, 011100006

OUT DX, AL

MOV CX, OOLOH

LO2: LOOP LO2

MOV DX, 20024

Mov AL, 000100006

OUT DX, AL

MOV DX, 2030H

MOV AL, 001100006

OUT DX, AL

MOV CX, DOIOH

LOB: 200P 203

MOV DX, 2001H

MOV AL, 001000006

OWT DX, AL

MOV DX, 2030H

MOV AL, 001 000006

OUT DX, AL

MOV ex, DOLD H

LOY: LOOP LOY

MOV DX, 2000 H

MOV AL, OIIIIIOb

OUT DX, AL

MOV DX, 2030H

MOV AL, 000000006

out Dx, AL

MOV DX, 2070H

MOV AL, 000000016

OUT DX, AL

MOV CX, 0060H

LOS: LOOP LOS

MOV DX, 2000 H

MOV AL, 011111006

OUT DX, AL

MOV DX, 2031H

mov AL, 001100016

out DX, AL

MOV CX, DOIDH

LOG: LOOP LOG

MOV DX, 2000H

MOV AL, 011110006

out px, AL

MOV DX, 2031H

MOV AL, 0011 00006

out DX, AL

MOV CX, DOIOH

LOF: LOOP LOF

MOV DX, 2000 H

MOV AL, 011100006

OUT DX, AL

MOV DX, 2031H

MOV AL, 001000006

out px, AL

Mov ex, 0010H

L08 : LOOP LOS

MOV DX, 2000H

MOV AL, 011000006

out DX, AL

MOV DX, 2031H

MOV AL, 000000000

out DX, AL

MOV DX, 2070H

MOV AL, 000000006

out DX, AL

MOV CX, 0060H

LOG: LOOP LOG

MOV DX, 2000H

MOV AL, 01000000b

OUT DX, AL

Loio: Loop loio

MOV CX, GOIOH

MOV PX, 2000H

MOV AL, 00000000b

OUT DX, AL

MOV CX, 0010H

LOII: LOOP LOII

MOV DX, 2001 H

MOV AL, 000000000b

OUT DX, AL

MOV CX, 0010H

L012: LOOP L012

MOV PX, 2002H

MOV AL, 000000006

OUT PX, AL

MOV CX, 0010H

L013: LOOP L013

MOV DX, 2003H

NOV AL, 00000100b

OUT DX, AL

MOV CX, 0010H

L014: LOOP L014

MOV DX, 2003H

MOV AL, 000000006

OUT DX, AL

MOV CX, 0010H

L015: LOOP L015

MOV DX, 2004H

MOV AL, 0000000066

OUT DX, AL

MOV CX, 0065H

L016: LOOP L016

DEC COUNT, O

CMP COUNT, O

JG PRINT

RET
MAIN ENDP
CSEG ENDS
END MAIN