

## **Ahsanullah University of Science and Technology (AUST)**

# **Department of Computer Science and Engineering**

## **LAB REPORT**

Course No : CSE3108

Course Title : Microprocessors Sessional

Assignment No : 05

Date of Submission : 12-02-2022

Submitted To : Ms. Tahsin Aziz & Ms. Tanjila Broti

# Submitted By:

Group : B1

Name : Anik Hassan Nibir

ID : 190104054

Section : B

## Question:

Dot Matrix: 'O A 5 H 4'

Seven Segment: 054

LED : RED1

#### Answen:

DSEG SEGMENT 'DATA'

DOT\_MATRIX DB 10H, 7FH, 12H, 14H, 18H, 7FH, 08H, 08H, 08H,

7FH, 31H, 49H, 49H, 49H, 2FH, 7EH, 09H,

09H, 09H, 7EH, 3EH, 41H, 41H, 41H, 3EH

COUNTER DB O

DSEG ENDS

SSEG SEGMENT STACK 'STACK'

DM 100 DMb (3)

SSEG ENDS

CSEG SEGMENT 'CODE'

START PROC FAR

push ps

MOV AX, DSEG

MOV DS, AX

MOV ES, AX

Mov Cx, O

#### DISPLAY:

MOV DX, 2070H

MOV AL, 00000001B

out DX, AL

MOV PX, 2001 H

MON AL, 00000001B

OUT DX, AL

MOV DX, 2002 H

MOV AL, 00000001 B

out Dx, AL

MOV DX, 2003H

MOV AL, 00000001B

out DX, AL

MOV DX, 2030H

MOV AL, 00000001B

out DX, AL

MOV CX, O4FH

LO: LOOP LO

MOV DX, 2004H

MOV AL, 00000010B

OUT PX, AL

MOV DX, 2004H

MOV AL, 00000110B

OUT DX, AL

MOV DX, 2004H

MOV AL, 00001110B

out DX, AL

MOV DX, 2004H

MOV AL, DOOIIII OB

out DX, AL

MOV DX, 2004H

MOV AL, DOIIIIOB

OUT DX, AL

MOV DX, 2030H

MOV AL, 00000011B

OUT DX, AL

MOV DX, 2030H

MOV AL, 00000111B

OUT DX, AL

MOV CX, OYFH

LI: LOOP LI

MOV DX, 2003H

MOV AL, 01000001B

OUT DX, AL

MOV DX, 2002H

MOV AL, 01000001B

OUT DX, AL

MOV DX 2001H

MOV AL, 01000001 B

out DX, AL

MOV DX, 2030H

MOV AL, 00001111B

out DX, AL

MOV CX, 64PH

L2: LOOP L2

MOV DX, 2000 H

MOV AL, 00100000B

OUT DX, AL

Mov DX, 20001+

MOV AL, 00110000B

OW PX, AL

MOV DX, 2000 H

MOV AL, 00111000B

OUT DX, AL

MOV DX, 2000H

MOV AL, 00111100B

out DX, AL

MOV DX, 2000H

MOV AL, COILLIIGB

OUT PX, AL

MOV DX, 2030H

MOV AL, DODILLILB

out DX, AL

MOV DX, 2030H

MOV AL, VOILILIB

out DX, AL

Mov CX, OUFH

L3: LOOP L3

MOV PX, 2005H

MOV AL, 01000000B

OUT DX, AL

MOV DX, 2005H

MOV AL, 01100000B

OUT DX, AL

mov DX, 2005H

MOV AL, OIII0000B

OUT DX, AL

MOV DX, 2005 H

MOV AL, OIIII000B

OUT DX, AL

MOV DX, 2005 H

MOV AL, OIIIIOOB

out DX, AL

MOU DX, 2005 H

MOV AL, OIIIIIOB

OUT DX, AL

MOV DX, 2006H

MOV AL, 00000001B

OUT DX AL

MOV DX, 2007 H

MOV AL, 0000000113

out DX,AL

MOV DX, 2008 H

MOV AL, 00000001B

OUT DX, AL

MOV DX, 2009H

MOV AL, 00000010B

OUT DX, AL

MOV DX, 2009 H

MOV AL, 00000110 B

OUT DX, AL

MOV DX, 2009H

MOV AL, COCOLITOB

OUT DX, AL

Mov Dx, 2009H

MUV AL, 0001111013

out DX AL

MOV DX, 2009H

MOV AL, DOILLIOB

OUT DX, AL

MOV DX, 2009H

MOV AL, OIIIIIOB

out DX, AL

MOV DX, 200614

MOV AL, 00001001B

OUT DX, AL

MOV DX, 2007H

MOV AL, 0000100113

out ox , AL

MOV DX, 2008H

MOV AL, 60001001B

OUT DX, AL

Mon Gx, ofth

LOG: Loop Log

MOV DX, 200EH

MOV AL, 00000001B

out DX, AL

MOV DX, 2000H

MOV AL, 00000001B

out DX, AL

MOV DX, 200CH

MOV AL, 00000001B

out DX, AL

MOV DX, 200314

MOV AL, DODOOODIB

out DX, AL

MOU DX, 200AH

MOV AL, 00000001B

but DX, AL

MOV DX, 2031H

MOV AL, 00000001B

OUT DX, AL

mov cx, o 4 FH

L4: LOOP L4

MOV DX, 200AH

MOV AL, 00000011B

out DX, AL

MOV DX, 200AH

MOV AL, 000001113

OUT DX, AL

MOV DX, 200AH

MOV AL, DODOLLIB

OUT DX, AL

MOV DX, 2031H

MOV AL, 0010000113

OUT DX, AL

MOU CX, OUFH

L5: LOOP L5

MOV DX, 200BH

MOV AL, 00001001B

out DX, AL

MOV DX, 200CH

MOV AL, 0000 100 B

out DX, AL

MOV DX, 2000 H

MOV AL, 00001001B

OUT DX, AL

MOV DX, 2031H

mov AL, 01100001B

OUT DX, AL

MOV CX, OUFH

L6: LOOP L6

MOV DX, 200EH

MOV AL, 0001000113

OUT DX, AL

MOV DX, 200Elt

MOV AL, 0011 0001B

OUT DX, AL

MOV Dx, 20314

MOV AL, OILOOIDIB

OUT DX, AL

MOV CX, OYFH

L7: 200p L7

MOV DX, 200 DH

MOV AL, 01001001B

OUT DX, AL

MOV DX, 200CH

MOV AL, 01 001001B

out DX, AL

MOV DX, 200BH

MOV AL, 01001001B

OUT DX, AL

MOV PX, 200 AH

MOV AL, 00101111B

out px, AL

MOV DX, 2031H

Mov AL, OIIOIIOIB

OUT DX, AL

MOV CX, OYFH

L8: LOOP L8

MOV DX, 200FH

MOV AL, 00000111B

out DX, AL

MOV DX, 200 FH

MOV AL, DODOLLIB

out DX, AL

MOV DX, 200FH

MOV AL, 00 11111113

out DX, AL

MOV DX, 2010 H

MOV AL, 00001000 B

OUT DX, AL

MOV DX, 2011H

MOV AL, 00001000B

out DX, AL

MOV DX, 2012H

MOV AL, 00001000B

OUT DX, AL

MOV DX, 2013H

Mov AL, 00000001B

OUT DX, AL

MOV DX, 2013H

MOV AL 000000118

OUT DX, AL

MOV DX, 2013H

MOV AL, DODODIIIB

OUT DX, AL

MOV DX 2013H

MOV AL, ODOOIIIB

OUT DX, AL

MOV DX, 20134

mov AL, DOOLLINB

OUT DX, AL

Mov DX, 2013H

MOV AL, DOILINB

OUT DX, AL

MOV DX, 2013H

MOV AL, OIIIIIIB

OUT DX AL

MOV ex oufH

LO4: LOOP LO4

Mov Dx, 2017H

MOV AL, 00000001B

out DX, AL

Mor Dx, 2016H

MOV AL, 0000001013

out DX, AL

MOU DX, 2015 H

MOV AL, 00000100B

OUT DX, AL

MOV DX, 2014H

MOV AL, 00001000B

out DX, AL

MOV DX 2032H

MOV AL, 00/00000B

out DX, AL

MOV CX, OUFH

L9: LOOP L9

Mov Dx, 2014H

MOV AL, 00011000B

out ox, AL

MOV DX, 2015 H

MOV AL, 00 01 01 00 13

OUT DX, AL

MOV DX, 2016H

MOV AL, 00010010B

OUT DX, AL

MOV DX, 2017H

MOV AL, 00010001B

OUT DX, AL

MOV DX, 2018H

Mov AL, 00010000B

OUT DX, AL

MOV DX, 2032H

MOV AL, 01100000B

OUT DX, AL

MOV CX, OUFH

L10: LOOP L10

MOV DX, 2017H

MOV AL, 000 10011B

out DX, AL

MOU DX 2017 H

MOV AL, 00010111B

OUT DX, AL

MOV DX 201714

MOV AL, DOOIIIIB

OUT DX, AL

MOV PX, 2032H

MOV AL, 0110001013

OUT DX, AL

MOV CX, OUFH

L11: LOOP 111

MOV DX, 201714

MOV AL, DOILIIIB

out DX, AL

MOV DX, 2017H

MOV AL, OIIIIIIB

out DX, AL

MOV DX, 2032H

MOV AL, OlloolloB

out DX, AL

MOV CX, OYFH

L12: LOUP L12

MOV COUNTER, O

Mov S1, 25

### CONTINUE:

MOU PX, 2018H

Mov CX, 26

DEC SI

INC COUNTER

CMP COUNTER, 26

JAE CLEARO

# SCROLL:

MOV AL, DUT\_MATRIX[SI]

OUT DX, AL

INC SI

DEC DX

CMP DX, 1FFFH

JBE CONTINUE

CMP S1, 25

JAE NEXT

LOOP SCROLL

# NEXT:

MOV SI, O

LOOP SCROLL

# CLEARO:

MOV CX, OYFH

L13 : Loop L13

MOV DX, 2070H

MOV AL, 00000000B

OUT DX, AL

Mov Dx, 2000 H

## CLEAR1:

MOV AL, 00000000B

out Dx, AL

INC CX

the DX

CMP CX, 26

JLE CLEAR1

MOV CX, OYFH

L14: LOOP L14

MOU DX, 2030H

MOV AL, 00000000B

out DX, AL

Mov DX, 2031 1+

mov AL, 00000000B

OUT DX, AL

MOV DX, 20324

MOV AL, 00000000B

out DX, AL

Mov ex, o

INC DI

cmp b1,5

JLDISPLAY

START EMOP

CSEG ENDS

END START