

Order ID: 332018052

Attn: Results Customer ID: HBI62

Healthy Buildings by UL Customer PO: 7862015983 3251 Old Lee Highway #100 Date Received: 10/07/20

Fairfax, VA 22030

Fax: 703-323-4440 LA Testing Order: 332018052

Phone: 571-655-7919

Email: <u>caresults@ul.com</u> Project: **2009049NY**

Report Date: 10/09/20 Date Analyzed: 10/09/20

Hydrogen Cyanide via NIOSH 6010 Modified (SKC226-210)

LA Testing ID	Sample ID	Volume (L)	Test Analyte	ug/tube	mg/m3	ppm	Reporting Limit (ug/tube)
332018052-0001	2004049NY-03A	13.29	Hydrogen Cyanide	<1.7	< 0.13	< 0.12	1.7
332018052-0002	2004049NY-03B	12.16	Hydrogen Cyanide	<1.7	<0.14	<0.13	1.7
332018052-0003	2004049NY-03C	NA	Hydrogen Cyanide	<1.7	NA	NA	1.7

LA Testing dba EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. Results in this report have not been blank corrected.

JD

Analyst

Michael Chapman, Laboratory Manager Or other approved signatory

michael Chapman