UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Tassal DeCosti	**Date:**	2nd November
Site Address:	29 Bachell ave Lidcombe	**Site Contact:**	Darryn.Hicks@tassal.com.au
		Phone:	
Customer PO		**Internal Job :**	5843

Subject: Speed line 1 Trave 1200

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 1000	00927	Skin line
Trave 1000	11377	High care MAP
Trave 1200	A16A-11326	Map
Trave 1000	12479	Tropica MAP

Equipment condition:

Work Performed:

Tuesday 2nd
Line 1 Trave 1200

- *Inspect line 1 Trave 1200 speed and reason for not running 80ppm recipe*
- *The 9x5 fast recipe was installed and production were running okay*
- *We could see a little movement during the step motion and this is due to wet belts and trays*
- *We installed an air knife and squeegee to reduce the amount of water and contamination on spacer belt.*
- *We tried to run the air hose through the main dump valve which is not working correctly and needs investigation as to why, due to production running we could not remove the dump valve which will need to be planned.*
- *The air-line has been connected directly to the main inlet air supply and we installed an isolation tap to activate the air knife for testing,*
- *Production needed to change over to 9x7 tool so we could do a complete test and will have to revisit.*

Line 3 Trave 1000

- *While we were on site we decided to inspect line 3 9x5 production run and noticed a few things*
- *The left side pusher arm gripper is damaged and needs replacing*
- *Production were running 9x7 chain recipe on 9x5 tool which runs slower*
- *We increase the speed from 40ppm to 51ppm and saved to the 9x5 recipe in chain line.*
- *We also need to install air-knife to reduce water and contamination.*

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes ☐	No☒
			Yes☐	No☒
			Yes☐	No☒

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

STATUS		
Machine Tested?	Yes☒	No☐
Comments:		
Revisit Required?	Yes☐	No☒
Comments:		

RECOMMENDATIONS
Comments:

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

TECHNICIAN HOURS	**Marc Ashford**	
Time	**Start**	**Finish**
Travel To Site:	07:00	07:30
Onsite:	07:30	11:30
Travel From Site:	11:30	12:00
Remote assistance:		
Report writing:	15min	
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X _____	2nd November
Technician:	Marc Ashford		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au