UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Lite N Easy	**Date:**	01/05/2025
Site Address:	18 Buchanan Road Banyo QLD 4014	**Site Contact:**	Lee Corcoran
		Phone:	
Customer PO #:		**Internal Job #:**	5392

Subject: Line 4 Lunch tool issue

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 340	A20/A-12496	Line 4

Equipment condition:

Good

Work Performed:

- Travel to site to investigate the problems with the lunch tool that is making bad sealing wrinkles on the trays.
- Inspected the top pressure valve to see if the diaphragm is in good condition and not bypassing air.
- Then We closed the top tool air opening to reduce the air intake and the vacuum suction to the top tool.
- We opened the top tool valve to ensure that the spring is in good condition.
- These made the machine seal better, but if we kept it like this, the tool would act differently in a different machine. So, we decided to investigate further.
- After some production time, we have stripped the bottom vacuum valve and discovered some plastic in front of the diaphragm. We believed this caused a starvation of vacuum in the bottom and created all the other issues.
- We have reverted to the original disk opening of the top tool to keep it uniform throughout the tools. The sealing was good.
- We left to go to MQF for some small job and came back again.
- Production said they had a few trays that looked like they were sucked in from time to time. We will come and investigate further tomorrow. We have arranged with Matt

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

GENERAL SERVICE REPORT

-

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
210000002131	cylinder	1	Yes ☐	No☒
			Yes☐	No☒
			Yes☐	No☒

STATUS		
Machine Tested?	Yes☒	No☒

UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Comments: Works good		
Revisit Required?	Yes☒	No☒
Comments:		

RECOMMENDATIONS
Comments: Replace the cylinder that we took from your stock

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

TECHNICIAN HOURS	**Jacques**	
Time	**Start**	**Finish**
Travel To Site:		
Onsite:	11:15	14:15
Travel From Site:	14:15	15:00
Remote assistance:	0	
Report writing:	30 Min	
Overnight stay	☐	
Overnight stay with flights	☐	

TECHNICIAN HOURS	**Paolo**	
Time	**Start**	**Finish**
Travel To Site:	05:30	06:30
Onsite:	06:30	14:15
Travel From Site:	14:15	15:15
Remote assistance:	0	
Report writing:	0 Min	
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Lee Corcoran	X _____	01/05/2025
Technician:	Jacques and Paolo		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au