UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Liteneasy WA	**Date:**	10/11/2025
Site Address:		**Site Contact:**	Sean
		Phone:	
Customer PO #:		**Internal Job #:**	SR5828
Subject: Line 2 Chainline timing			

Equipment Type:	Serial Number:	Customer Line # (if applicable):

Equipment condition:

Excellent

Work Performed:

I was requested by Sean to be onsite due to them having an issue with line 2. After investigation, I found the chain line timing out due to the chain line that jumped tooth on the sprocket. I suspect that the chain line was un-tensioned and washed which will explain why the situation existed. Corrected and the line was processing very good.

Sean also requested me to inspect line 1 where the transfer from the chain line onto the spacer belt which were not good. Re-adjusted the chain line height and timing of the spacer belt. Also loosen the sprocket at the end of the line as it was tight. Tested the line and all performed well.

RECOMMENDATIONS

Comments:

TECHNICIAN HOURS

Time	10/11/2025Start	10/11/2025Finnish			
Travel To Site:	07:45	08:45			
Onsite:	08:45	12:00			
Travel From Site:	12:00	12:30			

REPORT SIGN OFF

	Print Name:	Signature:	Date:
Customer:	Sean	X	10/11/2025
Technician:	Bertus Reynolds		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au