UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Liteneasy WA	**Date:**	12/03/2024
Site Address:		**Site Contact:**	Max
		Phone:	
Customer PO #:		**Internal Job #:**	SR4433
Subject: Line 2 Closer in delay alarm			

Equipment Type:	**Serial Number:**	**Customer Line # (if applicable):**
Trave 350 VG	A/17/A-11558	Line 2

Equipment condition:

Excellent

Work Performed:

I was requested by Max to attend to site as they were having issues with line 2.

Arrived onsite and investigate. Found that the pusher arm open and close were functioning very slow. Inspected and adjusted the speed of the pusher arm open and close movement. As a result, I had to make some adjustments to the recipe.

Because a mechanical adjustment was made to the machine, it is necessary to re-adjust the dinner tool as well, which has not been done yet. When production is running the dinner tool, it is important to notify me ahead so I can arrange to be onsite. Otherwise, I will install the dinner tool on the Uptime service and correct.

RECOMMENDATIONS

Comments:

TECHNICIAN HOURS

Time	**12/03/2024Start**	**12/03/2024Finish**			
Travel To Site:	06:30	07:30			
Onsite:	07:30	09:00			
Travel From Site:	09:00	10:00			

REPORT SIGN OFF

	Print Name:	**Signature:**	**Date:**
Customer:	Sean	X	12/03/2024
Technician:	Bertus Reynolds		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au