UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Hilton Foods Heathwood	**Date:**	15/02/2025
Site Address:	22 Seena place Heathwood	**Site Contact:**	Kane Bennet
		Phone:	0428 442 320
Customer PO #:		**Internal Job #:**	5015

Subject: Mondini line 2 film issue

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Mondini		Line 2

Equipment condition:

Work Performed:

Travelled to site
15/02/25
Remote assistance with customer. In the end customer asked for me to attend site on 16/02/25

16/02/25

Line 2 Found film blocking vacuum path cleaned and is working but needs to be cleaned completely.

Line 11 film tracking issue film is very wrapped operator was on to it adjusted film position to compensate however incorrect spreader cone is being used film draw rollers dirty or may need to be replaced.

Line 4 has meat caught in shuttle causing film transfer issues. Need to remove shuttle and clean.

Line 3 running ok looks like shuttle occasionally does not open correctly possible due to meat in shuttle. Need to remove shuttle and clean.

18/02/25
Returned to site assisted tool team to fit new seal bars and sand returning in the morning to support start up. Paper tool needs new insulating pad heater plates also top and middle bell as the blocking area is worn by 0.5mm and top bell clamp posts are stripping out

19/02/25
Arrived on site found operators cleaning tool film not lining up with tool found shuttle is wrong installed correct shuttle line ran well adjusted tool lift delay as film was a bit cold line running well.

Borrowed 1 vacuum bellows for Bindaree need to charge bindaree and send to Hilton Heathwood to Tandin.

71XAAAAI00003 x 1 VACUUM BELLOWS CONTACT Joey at bindaree

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
Purchase	Consumables sandpaper $250		Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

STATUS		
Machine Tested?	Yes☒	No☐
Comments: Good		
Revisit Required?	Yes☐	No☒
Comments: will be available for assistance		

RECOMMENDATIONS
Comments:

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

TECHNICIAN HOURS	15/02/25	
Time	**Start**	**Finish**
Travel To Site:		
Onsite:		
Travel From Site:		
Remote assistance:	09:00	13:00
Report writing:		
Overnight stay	☐	
Overnight stay with flights	☐	

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

TECHNICIAN HOURS	16/02/25	
Time	Start	Finish
Travel To Site:	06:00	07:00
Onsite:	07:00	13:00
Travel From Site:	13:00	14:00
Remote assistance:		
Report writing:		
Overnight stay	☐	
Overnight stay with flights	☐	

TECHNICIAN HOURS	18/02/25	
Time	Start	Finish
Travel To Site:	09:00	10:00
Onsite:	10:00	14:00
Travel From Site:	14:00	15:00
Remote assistance:		
Report writing:		
Overnight stay	☐	
Overnight stay with flights	☐	

TECHNICIAN HOURS	19/02/25	
Time	Start	Finish
Travel To Site:	05:00	06:00
Onsite:	06:00	10:00
Travel From Site:		
Remote assistance:		
Report writing:		
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	Signature:	Date:
Customer:	Kane Bennet	X	15/02/2025
Technician:	Paul Short		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au