UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Coles ROAA	**Date:**	15th August
Site Address:	54 Templar Rd, Erskine Park NSW 2759	**Site Contact:**	Alan Villa
		Phone:	0410 556 153
Customer PO #:		**Internal Job #:**	4096

Subject: Pusher arm placement

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 590	A17A-11614	Line 4
Platformer	A17A-11614	Line 4

Equipment condition:

Work Performed:

Tuesday 15th

- *Replacement of the pusher arms on the Trave 590*
- *The old damaged pusher arms were completely removed from machine*
- *The bushings and seals were removed and replaced*
- *Replaced the polish shafts and adjusts the stroke*
- *Test ran the pusher arms to make sure its running well.*

TECHNICIAN HOURS
Tuesday 15th

	Marc Ashford			Henry Nieuwenhuis	
Time	**Start**	**Finish**		**Start**	**Finish**
Travel To Site:	14:30	15:30		14:30	15:30
Onsite:	15:30	22:30		15:30	22:30
Travel From Site:	22:30	23:30		22:30	23:30

REPORT SIGN OFF

	Print Name:	Signature:	Date:
Customer:		X _____	15th August
Technician:	Marc Ashford		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au