UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Hilton Bunbury	**Date:**	16/03/2024
Site Address:	Rawling Road, Bunbury	**Site Contact:**	Scott
		Phone:	
Customer PO #:		**Internal Job #:**	SR4432

Subject: Replace pusher arm bushing and rods on Line 7

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 590		Line 7

Equipment condition:

Good

Work Performed:

Arrived onsite and with assistance of Allan Buckley, we replaced the bushing and rods on the pusher arms of line 7. At start up, we experienced servo drive errors on the open and close axis. After some fault finding, we fixed the problem and tested the machine.

Pusher arms were functioning fine without any problems.

TECHNICIAN HOURS

Time	16/03/2024Start	16/03/2024Finish			
Travel To Site:	06:30	08:00			
Onsite:	08:00	18:30			
Travel From Site:	18:30	20:00			

REPORT SIGN OFF

	Print Name:	Signature:	Date:
Customer:	Scott Mitchell	X _____	16/03/2024
Technician:	Bertus Reynolds		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au