UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Baiada Beresfield	**Date:**	20th January
Site Address:	Beresfield	**Site Contact:**	Mark Rooke
		Phone:	0401 704 186
Customer PO #:		**Internal Job #:**	5932
Subject: Callout			

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 590	A/21/A-12636	Value added L1
Trave 1000	A/15/A-11189	Value added L2
Trave590	A12A-00516	Value Added L3
E390	2857	Traypack Room 2
Trave 1000	A/16/A-11301	Traypack L2
Trave 1000	A/17/A-11735	Traypack L3
Trave 590	A23A-13202	TraypackL1

Equipment condition:

Breakdown

Work Performed:

Tuesday 20th

Line 1 Trave 1000 Tray pack 11x7 tool

- *Called out due to sealing problems on Line 1 tray-pack 11x7 tool*
- *We did a vacuum test and found the right side main vacuum hose was loose.*
- *We also found the gas regulator was set at 4.5 bar which should be around 2.5 to 3 bar and this would have caused the sealing problem by over pressure, once it was reduced to 3 bar the line ran well.*
- *Monitored production for a while and all ran good.*

Line 2 Trave 1000 Tray pack 9x7 tool

- *They were having problems with film tracking and wrinkles across the product.*
- *Removed the tool for inspection and found the outer bell was bend reason for not cutting film in one area, the bell had to be straightened.*
- *The tracking of film was caused by contaminated gummy rollers which we tried to clean.*
- *Change some film cycle speeds to reduce tracking.*
- *Watched production for a while and all seemed to run well.*
- *NOTE: the 9x7 tool needs replacing, this tool is in bad condition and not sure if possible to repair.*

Line 3 Trave 1000 Tray pack 9x7 tool

- *The tool locking valve was faulty and bypassed but causes the machine to unlock during the cycle.*
- *Replaced the faulty valve and tested which all worked*
- *Watched production and all ran well.*

TECHNICIAN HOURS	**Marc Ashford**	
Time	**Start**	**Finish**
Travel To Site:	06:00	08:00
Onsite:	08:00	12:30
Travel From Site:	12:30	14:30
Remote assistance:		
Report writing:	15min	
Overnight stay	☐	
Overnight stay with flights	☐	

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

GENERAL SERVICE REPORT

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X	20th December
Technician:	Marc Ashford		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au