UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Bindaree Beef	**Date:**	22/01/2026
Site Address:	6 Taree Street Burleigh Heads	**Site Contact:**	Joey
		Phone:	
Customer PO #:		**Internal Job #:**	5925

Subject: Line 2 Film Breaking and Flat pack issues.

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 590VGXL-S	A21A-12629	Line 2

Equipment condition:

Work Performed:

- Travel to site, sign in.
- Inspect machine operations, film breakage and flat pack reported in first pack non operator side.
- On monitoring operation, we found film slightly loose in the machine made some changes to the recipe, film unwinding infeed, film unwinding, deceleration, acceleration and waste rewind to keep tension on the film, also centralised the film to the tool. These adjustments helped the film breaking, however the waste cone directly after the tool were found to have stripped threads and unable to be adjusted correctly as they were moving and not tracking the waste film correctly. There is an upgrade from urethane to aluminium which will be quoted.
- Some minor adjustments were made to the vacuum settings the aid with the flat pack, and we were able to improve the issue, vacuum leaks were detected in the tool and will be addressed in the next uptime service, and the gummed rollers also require attention.
- The film waste was rewinding tightly and in a more uniform roll.
- Clean area and pack up.



Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

STATUS		
Machine Tested?	Yes☒	No☐
Comments: Good		
Revisit Required?	Yes☒	No☐
Comments:		

RECOMMENDATIONS
Comments: Luminium Cones requiredsc

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

TECHNICIAN HOURS	Scott	
Time	Start	Finish
Travel To Site:	10:30	12:00
Onsite:	12:00	16:30
Travel From Site:	16:30	18:00
Remote assistance:		
Report writing:	30 min	
Overnight stay	☐	
Overnight stay with flights	☐	

TECHNICIAN HOURS	Paul	
Time	Start	Finish
Travel To Site:	11:00	12:00
Onsite:	12:00	16:30
Travel From Site:	16:30	17:30
Remote assistance:	0	
Report writing:	0	
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	Signature:	Date:
Customer:	Joey. Leonard	_X_____	22/01/2026
Technician:	Paul and Scott		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au