UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Coles ROAA	**Date:**	27th February
Site Address:	54 Templar Rd, Erskine Park NSW 2759	**Site Contact:**	Alan Villa
		Phone:	0438 325 453
Customer PO #:		**Internal Job #:**	5225

Subject: TH300T FS M150 film trial

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 590	A17A-11614	Line 4
Platformer	A17A-11614	Line 4

Equipment condition:

Work Performed:

Thursday 27th

- *Arrived on site to run trials with the problem TH300 film and new batch of TH300*
- *While on site production were running the Mono film which was performing super well.*
- *We changed over to the new batch of TH300 inside sealant film with original KB9x8 recipe and it form okay with no issues*
- *We ran a few cycles sealing okay, but please note not as good as the Mono film.*
- *We tried the TH300 out sealant which did not work at all, not a single cycle was possible.*
- *We tried the problem TH300 inside sealant film which also ran okay not problem.*

After the meeting the decision was to supply new batch of TH300T film for production to run.

TECHNICIAN HOURS	**Marc Ashford**	
Time	**Start**	**Finish**
Travel To Site:	09:30	10:00
Onsite:	10:00	13:30
Travel From Site:	13:30	14:00
Remote assistance:		
Report writing:	30min	
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X _____	Thursday 27th
Technician:	Marc Ashford		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au