UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Liteneasy WA	**Date:**	29/01/2024
Site Address:		**Site Contact:**	Sean
		Phone:	
Customer PO #:		**Internal Job #:**	SR4338
Subject: Pusher arms missing the trays.(Line 2)			

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 350 VG	A/17/A-11558	Line 2

Equipment condition:

Excellent

Work Performed:

I was requested by Sean to be onsite due to the pusher arms that misses the trays on the spacer belt. Arrived onsite and investigate. Found the bearing on the chain line has collapsed and the chain line has lost its position.

Replaced the bearings on the sprocket and reset the position of the chain line.

Tested and all were functioning good.

RECOMMENDATIONS
Comments:

TECHNICIAN HOURS					
Time	**29/01/2024Start**	**29/01/2024Finnish**			
Travel To Site:	08:30	09:15			
Onsite:	09:15	12:45			
Travel From Site:	12:45	13:30			

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Sean	X _____	29/01/2024
Technician:	Bertus Reynolds		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au