UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Hilton	**Date:**	02/12/2025
Site Address:	22 Seena Place, Heathwood	**Site Contact:**	Kane Burnet
		Phone:	
Customer PO #:		**Internal Job #:**	5863

Subject: **Production Support various lines**

Equipment Type:	Serial Number:	Customer Line # (if applicable):

Equipment condition:

Work Performed:

Line1

- Checked up on line 1 and it seems to be running well.
- Only one pocket where the film was pulling back. Cleaned the dome and ok again. Spacers looks Like they are inside again.

Line 9

- Line 9 helping the team to identify why the shuttle is not going further than a cepoint in its cycle. Finding some air leaks and fixing that first

Line 2

- Line 2 tool doesn't seem to press down far enough to pick up the film. Almost not even touching the shuttle.
- Line 2 tool not going down properly
- We have removed the tool to grease and try and free up the push down shafts.
- Installed the tool and checked it still not coming down properly
- Made same spacers for shuttle line 2 like line1
- Even with spacer the tool doesn't seem like it's properly making Contact with shuttle. Removing the tool stops now
- I believe this tool may have to be revised.
- We then made an executive decision to remove this tool and to put in the 35mm tool for the rest of the production run. Before we could do this, I had to also take some parts from the bottom tool and place into the bottom tool of the 35mm dome tool.
- Tested the 35mm tool and it was working great.

Line 9

- Martina called me and said the pacers don't seem to work. I checked and found the valve bank in the bottom cabinet of the machine totally wrecked. I handed over to night shift.

GENERAL SERVICE REPORT



Line 9 valve bank a little bad in a bad state

3:42 pm

Back parts are broken and leaking air out. Hope there is spare parts for this

3:44 pm

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

STATUS		
Machine Tested?	Yes☒	No☐
Comments: Good		
Revisit Required?	Yes☐	No☐
Comments:		

RECOMMENDATIONS
Comments:

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

TECHNICIAN HOURS	**Jacques**	
Time	**Start**	**Finish**
Travel To Site:		
Onsite:	08:00	16:30
Travel From Site:	16:30	17:30
Remote assistance:		
Report writing:	30 Min	
Overnight stay	☐	
Overnight stay with flights	☐	

TECHNICIAN HOURS	**Paolo**	
Time	**Start**	**Finish**
Travel To Site:		
Onsite:		
Travel From Site:		
Remote assistance:		
Report writing:		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

GENERAL SERVICE REPORT

Overnight stay	☐
Overnight stay with flights	☐

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Kane Burnet, Diego Arguello	X	02/12/2025
Technician:	Jacques		