UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Coles RROA	**Date:**	3/2/22
Site Address:		**Site Contact:**	Rahul Sugumran
		Phone:	
Customer PO #:		**Internal Job #:**	3425

Subject: big tray map

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Platformer		

Equipment condition:

Normal

Work Performed:

Inspection found a lot of things wrong
Safety door latch broken need re-welding on back gate
Trays not forming well
Diffuser plates damage (broken bolts, missing pins, big drag marks up the face of the plates)

Trays are not being picked from tool on the pick & unload and causing issues with the following cycle as the trays are let behind in the tool.
Tried to fine tune recipe but couldn't achieve a good result with the forming and unload
Removed tool for inspection and install VSP to rule out machine
inspection found the upper diffuser plates were install in the machine with the wrong tool VSP diffuser plates and MAP bottom tool this explain why no change on any settings
VSP large tray was running fine
Removed pick and unload shuttle for inspection in workshop and found the lip mounding plates are bent and twisted.

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

GENERAL SERVICE REPORT

Stripped shuttle down to straighten plates.
Assemble shuttle and placed back into production.
Recommend replacing all the moulding lips plates as they are all bent and twisted don't float as freely as they should when assemble.

The reason for bending the lip mounding plates is the pressure transducer have been reduced down to where the machine doesn't detect that its missing a tray and cycles keep going building up in the bottom tool cavity until the height is too excessive which then bend the plates.

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

STATUS		
Machine Tested?	Yes☐	No☐
Comments:		
Revisit Required?	Yes☐	No☐
Comments:		

UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

RECOMMENDATIONS
Comments:

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

TECHNICIAN HOURS					
Time	**Start**	**Finish**		**Start**	**Finish**
Travel To Site:	8:00	9:30			
Onsite:	9:30	18:30			
Travel From Site:	18:30	20:00			

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Dave Thomas	x	3/2/22
Technician:	Tim Harrison		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au