UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Liteneasy WA	**Date:**	30/01/2024
Site Address:		**Site Contact:**	Sean
		Phone:	
Customer PO #:		**Internal Job #:**	SR4347
Subject: New line 3 needs adjustment with the product.(Sucking product)			

Equipment Type:	Serial Number:	Customer Line # (if applicable):

Equipment condition:

Excellent

Work Performed:

I was requested by Sean to be onsite due to them having an issue with the product that is being sucked out of the tray causing the leaves to be on the side of the tray when sealing.

Investigate and found that the gas pressure was too high for this product. I adjusted the gas pressure in the machine back from 3 Bar to 2 Bar. All looked good.

Production measured the gas inside the trays which was not good. I investigate and after a bit of fault-finding, I raised the vacuum position about 5mm and then the gas measurements were good.

RECOMMENDATIONS
Comments:

TECHNICIAN HOURS					
Time	**30/01/2024Start**	**30/01/2024Finnish**			
Travel To Site:	09:30	10:30			
Onsite:	10:30	13:00			
Travel From Site:	13:00	13:45			

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Sean	X	30/01/2024
Technician:	Bertus Reynolds		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au