UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Hilton foods Truganina	**Date:**	5th August
Site Address:	Victoria Melbourne	**Site Contact:**	George Karagounis
		Phone:	048702 2551
Customer PO #:		**Internal Job #:**	5589

Subject: Tool VIC 5009

Equipment Type:	**Serial Number:**	**Customer Line # (if applicable):**
Medium DOT	VIC5009	Line 3 Trave 590

Equipment condition:

Work Performed:

Tuesday 5th

Line 3 VIC 5009

- *Arrived and production had already started with some sealing issues Gabs was investigating*
- *Started making some changes the recipe for release time before it started running well.*
- *We do have a problem with one of the dome plates not always forming but this we believe is due to in not been flat, if the problem gets any worse the dome will be replaced.*
- *The tool cycle is faster than before reaching 40ppm up by 10ppm.*
- *Fine tune and cleaned up the recipe while in full production with the only concern is the non Mondini infeed belt system allowing double tray through.*
- *Watched production for a while and all looked okay, the recipe was saved under "D"*

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

GENERAL SERVICE REPORT

TECHNICIAN HOURS	Marc Ashford	
Time	**Start**	**Finish**
Travel To Site:	05:30	06:00
Onsite:	06:00	11:30
Travel From Site:	11:30	17:00
Remote assistance:		
Report writing:	30min	
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X _____	5th August
Technician:	Marc Ashford		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au