UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Baiada Beresfield	**Date:**	8th December
Site Address:	Beresfield	**Site Contact:**	Mark Rooke
		Phone:	0401 704 186
Customer PO #:		**Internal Job #:**	5870
Subject: Callout			

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 590	A/21/A-12636	Value added L1
Trave 1000	A/15/A-11189	Value added L2
Trave590	A12A-00516	Value Added L3
E390	2857	Traypack Room 2
Trave 1000	A/16/A-11301	Traypack L2
Trave 1000	A/17/A-11735	Traypack L3
Trave 590	A23A-13202	TraypackL1

Equipment condition:

Breakdown

Work Performed:

Monday 8th

- *Called out due to pusher arm no 2 error on line 2 Tray pack.*
- *Removed no 2 pusher arm to gain access to servo motor to inspect the resolver cable plug.*
- *Reconnected and spray contact cleaner in plug*
- *Removed and inspect D-sub 9 pin female port for Servo drive.*
- *Open the female plug and resolder the connection which looked suspect.*
- *Reboot the system and watched production run.*
- *The operator was happy with pusher arm having no error while on site.*

TECHNICIAN HOURS	**Marc Ashford**	
Time	**Start**	**Finish**
Travel To Site:	05:30	07:30
Onsite:	07:30	10:30
Travel From Site:	10:30	12:30
Remote assistance:		
Report writing:	15min	
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X _____	8th December
Technician:	Marc Ashford		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au