UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Baiada Hanwood	**Date:**	26/07/2025
Site Address:	Hanwood (Griffith)	**Site Contact:**	Wayne Thomas
		Phone:	0436 194 771
Customer PO #:		**Internal Job #:**	4617

Subject: Uptime service

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 590	A/18/A-11913	Line 1
Trave 590	A/18/A-11912	Line 2
Trave 590	A/18/A-12013	Line 3
Trave 590	A/21/A-12796	Line 4
Trave 590	A/21/A-12795	Line 5
Trave 350	A/24/A-13414	Line 6

Equipment condition:

Work Performed:

26/07/2025

Arrive on site at 07:00, production were running. Line 4 and 5 were given to us to service

Trave 590 Line 4 - A/21/A-12796

Mondini line 4 was inspected and serviced. The Tool, pusher assembly, Belts, rollers Film unwind roller, Film drive, Scrap roller, Covers, Vacuum circuit, Pneumatic system, Lubricating system was inspected serviced and tested.

- *Replaced infeed and spacer belt bearings 6001 2RS*
- *Replaced infeed and spacer belt Teflon gears bearings 6000 2RS*
- *Replaced red O cord*
- *Replaced T seal*
- *Replaced punching knives 11x9*
- *Replaced 2 belts on pusher arms open and close.*
- *Tested Heater element and PT 100.*
- *Replaced vacuum and gas O-rings*
- *Tested gas ports*
- *Inspected foot springs.*
- *Adjusted lower tool locking system*
- *Inspected top diaphgram still good*
- *Replaced bearing on Deviator belt*

Note: Gummi rollers needs to be replaced, none in stock

GENERAL SERVICE REPORT

Line 5
Trave 590
Serial number: A/21/A-12795

Inspected Mondini line 5 was inspected and serviced. The Tool, pusher assembly, Belts, rollers Film unwind roller, Film drive, Scrap roller, Covers, Vacuum circuit, Pneumatic system, Lubricating system was inspected and tested.

- *Inspected reflectors*
- *Replaced red O cord.*
- *Inspected seal bars and cleaned.*
- *Replaced 11x7 punching knifes*
- *Tested Heater element and PT 100*
- *Replaced T seal for bottom tool.*
- *Replaced two foot springs*
- *Greased bottom tool.*
- *Inspected in feed and spacer belts.*
- *Infeed belt, spacer belt bearings replaced 6001 2RS, 12 of them*
- *Infeed, spacer belt Nylon gear bearings replaced 6000 2RS, 8 of them*
- *Inspected bearings on open and close of pusher arms*
- *Inspected belts on the pusher arms*
- *Lubricated tools and machine*
- *Lubricated ext belts*
- *Tested lubrication system*
- *Inspected vacuum pipes*
- *Did vacuum test*
- *Replaced pnuematic card on locking system of infeed film*
- *Inspected top diaphram*
- *Inspected blue exit cords, needs to be replaced.*
- *Replaced sleeved roller infeed belt*

Note

- *No blue exit cords in stock*
- *No gummi rollers in stock*
- *Not infeed belts in stock*

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes ☐	No☐

STATUS		
Machine Tested?	Yes☐	No☐
Comments:		
Revisit Required?	Yes☐	No☒
Comments:		

- **Comments**

TECHNICIAN HOURS	**Marc Ashford**	
Time	**Start**	**Finish**
Travel To Site:	06:30	07:00
Onsite:	07:00	15:00
Travel From Site:	15:00	15:30
Remote assistance:		
Report writing:		
Overnight stay	☒	
Overnight stay with flights	☐	

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

TECHNICIAN HOURS	Henry Nieuwenhuis	
Time	**Start**	**Finish**
Travel To Site:	06:30	07:00
Onsite:	07:00	15:00
Travel From Site:	15:00	15:30
Remote assistance:		
Report writing:		
Overnight stay	☒	
Overnight stay with flights	☐	

TECHNICIAN HOURS	Tim Harris	
Time	**Start**	**Finish**
Travel To Site:	06:30	07:00
Onsite:	07:00	15:00
Travel From Site:	15:00	15:30
Remote assistance:		
Report writing:		
Overnight stay	☒	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X _____	30/07/2025
Technician:	Marc Ashford / Henry Nieuwenhuis/ Tim Harris		