UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Baiada Hanwood	**Date:**	27/07/2025
Site Address:	Hanwood (Griffith)	**Site Contact:**	Wayne Thomas
		Phone:	0436 194 771
Customer PO #:		**Internal Job #:**	4617

Subject: Uptime service

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 590	A/18/A-11913	Line 1
Trave 590	A/18/A-11912	Line 2
Trave 590	A/18/A-12013	Line 3
Trave 590	A/21/A-12796	Line 4
Trave 590	A/21/A-12795	Line 5
Trave 350	A/24/A-13414	Line 6

Equipment condition:

Work Performed:

26/07/2025

Arrive on site at 07:00, no production. All lines were available.

Line 3
Trave 590,
Serial number: A/18/A-12796

Inspected Mondini line 3 was inspected and serviced. The Tool, pusher assembly, Belts, rollers Film unwind roller, Film drive, Scrap roller, Covers, Vacuum circuit, Pneumatic system, Lubricating system was inspected.

- *Inspected reflectors*
- *Replaced red O cord.*
- *Inspected seal bars and cleaned.*
- *Inspected punching knifes*
- *Tested Heater element and PT 100*
- *Replaced T seal for bottom tool.*
- *Greased bottom tool.*
- *Inspected in feed and spacer belts.*
- *Infeed belt, spacer belt bearings replaced 6001 2RS, 12 of them*
- *Infeed, spacer belt Nylon gear bearings replaced 6000 2RS, 8 of them*
- *Inspected bearings on open and close of pusher arms*
- *Inspected belts on the pusher arms*
- *Lubricated tools and machine*
- *Lubricated ext belts*
- *Tested lubrication system*

GENERAL SERVICE REPORT

- *Inspected vacuum pipes*
- *Did vacuum test*
- *Inspected top diaphram*
- *Fixed door which had missing bolt for swing arm*
- *Set door gap so pusher arms don't rub.*
- *Reaplaced broken circli on idle roller*
- *Replaced missing keys on dancing rollers*

Note

- *No gummi rollers in stock, needs replacement.*
- *Pusher arm column is damaged needs replacement will send quote.*

Line 1
A/18/A-11913

- *Inspected reflectors*
- *Replaced red O cord.*
- *Inspected seal bars and cleaned.*
- *Inspected punching knifes replaced the complete set. 8x5 size*
- *Tested Heater element and PT 100*
- *Replaced T seal for bottom tool.*
- *Greased bottom tool.*
- *Inspected in feed and spacer belts.*
- *Replaced spacer belts worn out.*
- *Infeed belt, spacer belt bearings replaced 6001 2RS, 12 of them*
- *Infeed, spacer belt Nylon gear bearings replaced 6000 2RS, 8 of them*
- *Inspected bearings on open and close of pusher arms*
- *Inspected belts on the pusher arms*
- *Lubricated tools and machine*
- *Lubricated ext belts*
- *Tested lubrication system*
- *Inspected vacuum pipes , replace one of them.*
- *Did vacuum test*
- *Inspected top diaphram*

Note:

- *White mobile nylon block needs replacing*
- *8x5 needs new tray lifter which is damaged*
- *8x5 recipe home was set to high which is damaging the lower tool caused by pusher arm rubbing.*
- *Gummi rollers needs replacement. None in stock.*
- *Infeed belt Gummed roller needs replacement*

GENERAL SERVICE REPORT

Line 2
A/18/A-11912

- *Inspected reflectors*
- *Replaced red O cord.*
- *Inspected seal bars and cleaned.*
- *Foam pads needs replacing*
- *Inspected punching knifes replaced the set of 11x7 kifes.*
- *Tested Heater element and PT 100*
- *Replaced T seal for bottom tool.*
- *Greased bottom tool.*
- *Inspected in feed and spacer belts.*
- *Replaced spacer belts worn out.*
- *Infeed belt, spacer belt bearings replaced 6001 2RS, 12 of them*
- *Infeed, spacer belt Nylon gear bearings replaced 6000 2RS, 8 of them*
- *Inspected bearings on open and close of pusher arms*
- *Inspected belts on the pusher arms*
- *Lubricated tools and machine*
- *Lubricated ext belts*
- *Tested lubrication system*
- *Inspected vacuum pipes , replace one of them.*
- *Did vacuum test*
- *Inspected top diaphram*
- *Replaced broken circlips on idle rollers*
- *Found vacuum port bolt loose*

Notes

- 11x7 tool tray lifter needs replacement with correct bushings for tray lifter
- Infeed belt needs replacing, none in stock

Line 6
A/24/A-13414

- Inspected knifes and cleaned them
- Cleaned seal bars
- Replaced red O cord
- Greased top tool
- Inspected bellows
- Replaced T seals
- Inspected foot springs and foot plate
- Replaced 123 O rings
- Greased bottom tool

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

- Tested Grease pump and filled up grease pump
- Inspected vacuum pipes
- Inspected film system
- Did vacuum test

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes ☐	No☐

STATUS		
Machine Tested?	Yes☐	No☐
Comments:		
Revisit Required?	Yes☐	No☒
Comments:		

- **Comments**

TECHNICIAN HOURS	**Marc Ashford**	
Time	**Start**	**Finish**
Travel To Site:	06:30	07:00
Onsite:	07:00	15:30
Travel From Site:	15:30	16:00
Remote assistance:		
Report writing:		
Overnight stay	☒	
Overnight stay with flights	☐	

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

TECHNICIAN HOURS	Henry Nieuwenhuis	
Time	**Start**	**Finish**
Travel To Site:	06:30	07:00
Onsite:	07:00	15:30
Travel From Site:	15:30	16:00
Remote assistance:		
Report writing:		
Overnight stay	☒	
Overnight stay with flights	☐	

TECHNICIAN HOURS	Tim Harris	
Time	**Start**	**Finish**
Travel To Site:	06:30	07:00
Onsite:	07:00	15:30
Travel From Site:	15:30	16:00
Remote assistance:		
Report writing:		
Overnight stay	☒	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X _____	30/07/2025
Technician:	Marc Ashford / Henry Nieuwenhuis/ Tim Harris		