UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	RROA Coles	**Date:**	01.12.2025
Site Address:	Unit 54/72 Templar Rd, Erskine Park NSW 2759	**Site Contact:**	Engela Nieuwenhuis
		E-mail:	Engela.Nieuwenhuis@coles.com.au
Customer PO:		**Internal Job**	5862

Subject: RRROA Callout Platformer (5862)

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Platformer	A17A-11614	

Equipment condition:

Serviceable condition.

Work Performed:

01 December 2025

Platformer A17A-11614

- Arrived at site and investigate.
- Found that film infeed belt was tracking a lot.
- Released the tension on the belt. Tension was set way too high again.
- Had to adjust the side tensioners to stop the belt from tracking to the left.
- Belt was running straight and was not tracking any more.
- Need to make sure there is a spare belt in the store. This belt has been stretched.
- Found that the last tray on the tool does not form well.
- Made adjustments to recipe and could not get it better.
- I set the system to only make 4 trays until I the Platformer could be stopped.
- After production was done I got access to the machine.
- I removed the diffuser plates from the machine. Clean and inspect them and made sure all ports are open
- Diffuser plates are not in very good condition. Heat transfer might be a problem.
- I inspected the magnets on the Drum and all of them were in serviceable condition.
- I replaced the 3.5mm red ORCORD on the diffuser plates and put them back in to test them.
- Problem was still there.
- The problem was only occurring on the one diffuser, so I swapped the diffuser plates to see if the fault follows. After this was done both sides were not forming well on the last tray.

GENERAL SERVICE REPORT

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
1751	3.5mm red ORCOPRD	6	Yes ☐	No☒

STATUS		
Machine Tested?	Yes☐	No☐
Comments: Good		
Revisit Required?	Yes☒	No☐

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**
710000152137	Belt XVT	1

TECHNICIAN HOURS	Johan	
Time	**Start**	**Finish**
Travel To Site:	09:00	09:30
Onsite:	09:30	17:00
Travel From Site:	17:00	17:30
Remote assistance:		
Report writing:	30 min	
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:			01.12.2025
Technician:	Johan		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au