UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Huon Aquaculture	**Date:**	11/02/2026
Site Address:	7218 Bass Highway East SASSAFRAS Tasmania	**Site Contact:**	Anthony
		Phone:	0428776039
Customer PO #:		**Internal Job #:**	5998

Subject: Pusher arms not functioning correctly.

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 340	A/14/A-00912	Skin Line

Equipment condition:

Work Performed:

- Arrived on site and met with Anthony. The issue on the line was resolved the previous day in the afternoon. K8 card was swapped out.
- Went to line and monitored production for +- 2hours. Line was running consistent and pusher arms was functioning correctly.
- When production team when for their toolbox talks, we inspected the line.
- We found a lot of water present in the air system. Water tarp on the air service unit in the Mondini was full of water and we could see water drops in all of the air lines. This need to be rectified as soon as possible as it will cause lot of issue with the pneumatic valve bank.
- We switched off the air and drained the water trap.
- Tested grease pump. All good
- Adjusted infeed bely position as it was not properly in place and causing a high spot on the infeed side turning trays as the transfer form chain line.
- We also noticed the following that need attention
    1. One of the knifes on the tool is loose and hanging lower than the seal bar.
    2. Seal bars are very dirty and needs to be cleaned. Teflon coating must also be inspected as it looks worn.
    3. Chians tension on chain line must be adjusted.

Also had a quick look at the Mondini in the shed to see if it is skin ready. The line is not ready for skin as it has none of the required skin valves. Also confirmed on the drawing for the line.

Left site and arranged travel back to Adelaide.

STATUS

TECHNICIAN HOURS	**David van der Merwe**	
Time	**Start**	**Finish**

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Travel To Site:	7:30	8:00
Onsite:	8:30	10:30
Travel From Site:	10:30	22:30
Remote assistance:		
Report writing: (12/02/2026)	9:00	9:30
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Anthony	_X_____	11/02/2026
Technician:	David		