SIMPLYMICHIGAN INFOTAINMENT

SCAN ME

Need support? Please visit our support website or contact us
https://support.simplymichigan.co or scan the QR code
Reach us at nick@simplymichigan.co

Thank you for your purchase! We greatly appreciate the business. You've helped our small business and other small businesses around the United States via our local and national supply chain. Our goal is to supply you with the best service possible without having to cut corners like our Chinese competition (or charge you double the price for it like our other larger .com competition)

Your purchase includes a 1 year warranty on all hardware from the date you receive it, unless you purchased SimplyCare, in which case the expiration of the warranty will be 3 years from the date of purchase. **The sticker on the hardware includes our internal inventory number and the VIN from the donor vehicle (if available)**. Please keep this information for your records.

Basic universal instructions are listed on the back of this page for replacing your APIM module. If you need a visual guide we recommend finding a video on YouTube for precise instructions for your exact model and year (not available for every model). If you need help finding a video please reach out and we can help.

SIMPLYCARE

Everyone runs into some bad luck and hardware failures do occasionally happen, it's not too late to protect yourself from an unexpected failure and future repair expenses for two extra years (for a total of 3 years). Covers full replacement if necessary. Save $10 by using coupon code 3YEARS. Scan QR or go to https://b.link/kv2tpcnq

SCAN ME

Thank you again for your support! If you have any concerns, suggestions or if you're in need of technical support please don't hesitate to reach out to us, we're always here to help. **Spreading the word about your great experience on Facebook, vehicle message boards, YouTube, Reddit, etc. is greatly appreciated and helps us immensely, you may even found out about us this way yourself. We would be very grateful for your recommendation.**

UNIVERSAL BASIC INSTRUCTIONS (APIM Replacement)

1. Remove the climate/HVAC control panel surrounding your current display. Typically there's around 4-6 7MM bolts that you will need to remove to disconnect the bezel and/or display screen however your vehicle may differ. To get to the bolts Ford/Lincoln uses retention clips to hold most of the dash together. Giving them a good tug usually will separate them. Plastic pry tools can also be used. Before pulling the bezel away from the dash be sure to disconnect any wiring for your controls. A youtube video for your specific vehicle may be helpful if you're unsure of where to start.

2. Use a 7MM socket and remove the bolts holding the screen to the vehicle. Slowly pull the screen out, reach behind the display and start disconnecting the wires. Disconnecting the battery is not necessary, just make sure that the radio is off before you disconnect it. For the main vehicle wiring harness, push in the tab on the top/middle of the harness and pull the lever back, this will pull the connector out of the APIM. For the GPS antenna and the USB cord, push down the clip and SLOWLY wiggle the connector back and fourth until it loosens, then remove. The GPS antenna connector is fragile and can get damaged if you use a lot of force.

3. Remove the APIM from the display using a phillips screwdriver. Disconnect the LVDS cable connecting the display and the APIM together.

4. Take your replacement Sync 3 APIM and move it into place behind the display and reconnect it with the screws you removed in step 2 and reconnect the display cable.

5. Re-install the 7MM bolts to secure the display and module to the vehicle.

6. Re-assemble your dash, going in reverse. Remember to re-connect all wiring. Be careful with those 7MM bolts, if you drop them while trying to screw them back in you might lose them inside the dash.

7. Turn on your vehicle and let the system boot up. It's important to go to the SETTINGS menu, click GENERAL then scroll to the bottom and click "Master Reset", this should wipe the slate clean (don't worry, your programming won't be effected) so you won't run into any weird glitches later.

8. Enjoy your now working Sync 3 infotainment system! **If you run into any issues do another master reset. Then do a soft reset by holding down the power button and the forward seek button for 5-10 seconds until the radio shuts off and restarts. If you continue to have problems please reach out to us for further assistance. Doing these resets fixes most issues after installation.**