

**INVOICE** 

Remit To: PO Box 970

Cherryville, NC 28021

800-438-8961

Advertisement

(p) 12/31/2018 15:06

Ask about our Asset Relocation program. 1-855-836-3912

Invoice Num	4924644C
Invoice Date	12/31/2018
Customer PO	344-4924644

FEDEX GROUND-OCALA, FL HUB FXG0344

ATTN: SENIOR MANAGER 3100 NW 35TH AVE ROAD BUILDING #200

OCALA, FL 34475

and the second	Units
	Involved:
	► = Unit(s) Serviced

Bill To:

Tractor >	144496	2nd Trailer	825162
Trailer	55669	2nd Dolly	**************************************
Dolly	610825	3rd Trailer	

## Nature of Trouble

DRIVER ADVISED ADVISED THE LRO TIRE BLOWN ON TRUCK ---- NO OTHER DAMAGES ----29575R22 5----DRIVER DID NOT HAVE T-CHECK----ENTER CC # FOR FORM OF PAYMENT

## Instructions to Driver

Repairs Major VMRS Code: 017-001-020

SERVICE CALL FOR THE LRO TIRE BLOWN ON TRUCK. TECH REPAIRED THE LRO TIRE WITH A PATCH. BILL TO FLEETNETS FEDEX GOODYEAR NATIONAL ACCOUNT. MISC. CHARGE DUE TO FUEL SURCHARGE.

**Event Notes** (Most recent listed first, space permitting)

Dec 17 2018 9:25AM - Called Vendor for Status Update. - Caroline

Dec 17 2018 8:55AM - Called to notify TONY HULAN that a vendor has been assigned: Answered.. - Caroline

Cost Summary (US	Dollars)
Parts	\$0.00
Labor	\$163.50
Vendor Service	\$0.00
Wrecker	\$0.00
Mileage	\$22.40
Misc	\$2.40
Tire Cost	\$0.00
Tire Disposal	\$0.00
Tire FET	\$0.00
Sales Tax	\$0.17
FleetNet Svc	\$53.42
Terms Fee	\$0.00
Total Due	\$241.89
Due by Wednesday, January 30	0, 2019 or late

penalties will be incurred

Event Details				
Location	HARDEEVILLE, SC			
Driver	TONY HULAN			
Called In	12/17/2018 8:45:00 AM EST			
Started	12/17/2018 9:30:00 AM EST			
Completed	12/17/2018 10:00:00 AM EST			
Hours for Repair	0.50			
Hours Down	1.25			
Odometer/Hub	AND THE RESIDENCE OF THE PROPERTY OF THE PROPE			
Vendor	GAS2702			
VIN#	4V4NC9EJ9HN965039			
Tire Size	29575R22.5			
Tire Location	LRO			
Tire REPL Reason	PUNCTURE			

12-31-18