487. At what angle do vent stacks attach to horizontal vent pipes?

(a) 90 degrees

(c) 22 ½ degrees

(b) 45 degrees

(d) 60 degrees

- 488. If ever pipes are to pass through masonry by using pipe sleeves, how far must each pipe be from each other?
 - (a) Minimum of three diameters, center to center
 - (b) Minimum of three diameters flushed from each hole
 - (c) Minimum of 0.15 m on centers
 - (d) Maximum of two diameters flushed from each hole