112. When joints are necessary in a copper gas piping system, what type of solder must be used?

(a) Hard

(c) Malleable

(b) Soft

(d) Ductile

112. When joints are necessary in a copper gas piping system, what type of solder must be used?

(a) Hard

(c) Malleable

(b) Soft

(d) Ductile