358. What is the copper content in brass fitting?

(a) 80%

(c) 90%

(b) 85%

(d) 95%

358. What is the copper content in brass fitting?

(a) 80%

(c) 90%

(b) 85%

(d) 95%