- 553. What should be done whenever a partition contains some piping and runs parallel to the floor joist underneath?
 - (a) Notching should be introduced into the joist
 - (b) Adjust the joist to make it perpendicular with the direction of pipe
 - (c) Space the joist wider to accommodate the pipe
 - (d) Double the joist

- 553. What should be done whenever a partition contains some piping and runs parallel to the floor joist underneath?
 - (a) Notching should be introduced into the joist
 - (b) Adjust the joist to make it perpendicular with the direction of pipe
 - (c) Space the joist wider to accommodate the pipe
 - (d) Double the joist