697. Joints at the roof around stack vent pipes shall be made water-tight by the use of approved.

(a) Bitumen

(c) Pipe sleeve

(b) Flashing materials

(d) Epoxy

698. Riser diagrams, which are elevations or perspective views showing stacks and risers generally indicate what kind of jobs?

(a) Simple

(c) Complicated

(b) Non-complicated

(d) Easy