486. The National Master Plumbing Association of the Philippines (NAMPAP) was organized and registered with the Securities and Exchange Commission in what year?

(a) 1933

(c) 1935

(b) 1934

(d) 1945

487. At what angle do vent stacks attach to horizontal vent pipes?

(a) 90 degrees

(c) 22 ½ degrees

(b) 45 degrees

(d) 60 degrees