429. The indirect waste lines carrying refrigeration waste shall not be smaller than one (1) inlet serving not more than 2.8 mm³ of refrigeration space.

(a) 32 mm

(c) 76 mm

(b) 51 mm

(d) 62 mm

- 430. Who has the power to remove any member of the Board of Master Plumbers for neglect of duty, incompetence, malpractice, and unprofessional or dishonorable conduct?
 - (a) President of the Philippines
 - (b) Civil Service Commissioner
 - (c) Chairman of PRC Commissioners
 - (d) Commission on Appointments