167. Normally, a _____ mm/hr rainfall intensity is used around Metro Manila.

(a) 100

(c) 150

(b) 450

(d) 175

168. Current chairman of PRC board for Master Plumber.

(a) Virgillo Simbulan

(c) Valentino Mangila

(b) Pedrito Camilet

(d) Reynald Ilagan