37. The soil branch piping installed in horizontal run must be supported by a substantial iron hanger at close interval to prevent sagging, approximate a distance

(a) 1.50 meters apart

(c) 1.00 meters apart

(b) 2.00 meters apart

(d) 3.50 meters apart

38. Which of the following fixtures does NOT belong to the group?

(a) Hose bibb

(c) Water cooler

(b) Water spigot

(d) Water faucet