736. Which type of fire line installation has become obsolete and seldom installed?

(a) Automatic system

(c) Local vent

(b) Wet standpipe

(d) Dry standpipe

736. Which type of fire line installation has become obsolete and seldom installed?

(a) Automatic system

(c) Local vent

(b) Wet standpipe

(d) Dry standpipe