


[illegible]

Test Pins



PWR References

The diagram illustrates the power reference connections for a device. It shows a JP1 header with two pins. Pin 1 is connected to a ground symbol (GND). Pin 2 is connected to a +3V3 supply. The +3V3 supply is also connected to a PWR_FLAG pin, which is also connected to a ground symbol (GND).