Z1:	Gewichtmessen
gk:	1
gs:	1

Z11:	Funktionserfüllung
gk:	0.4
gs:	0.4

	δ ³ .	0.4	0.4	
Z111:	Platzbedarf/ Integriebarkeit	Z112:	Messbereich	
gk:	0.6	gk:	0.4	
gs:	0.24	gs:	0.16	

Z12:	Umsetzbarkeit		Z1
gk:	0.35		gk
gs:	0.35		gs
Z121:	Einfachheit	Z131:	Fe
gk:	1	gk:	
gs:	0.35	gs:	

Z13:	Kosten		
gk:	0.25		
gs:	0.25		
	7404	_	-

Z131:	Fertigung	Z131:	Zukaufteile
gk:	0.4	gk:	0.6
gs:	0.1	gs:	0.15

Variante1	Variante2	Variante3	Variante4	Variante5
_m_i m_i * g_s	_m_i	m_i * g_sm_i	_m_i * g_s _m_i	_m_i * g_s _m_i m_i * g_s
8	1.92 6	1.44 10	2.4 6	1.44 8 1.9
10	1.6 10	1.6 10	1.6 10	1.6 10 1.
10	3.5 6	2.1 10	3.5 8	2.8 10 3.
8	0.8	0.8 10	1 9	0.9 10
5	0.75 4	0.6 4	0.6 1	0.15 7 1.0
Gesamt:	8.57 Gesamt:	6.54 Gesamt:	9.1 Gesamt:	6.89 Gesamt: 9.0