$$Q(x) = \begin{cases} 406.52 \cdot x^{6.19} & \text{if } x \le 0.1968 \text{ m} \\ 1.63 \cdot x - 0.3 & \text{if } x > 0.1968 \text{ m} \end{cases}$$