## Exercise 1

In a production of sheets metal, data was collected regarding the causes that generated sheet metal failures. The data was divided into two groups concerning morning and evening shifts. Choose which type of graphic representation allows me to understand what the main causes of failures are and implement it in matlab. Create a dataset that from the starting data allows me to implement a C control chart.