SOP-021 CAPA Management - Page 1

Section 1. Purpose and Overview:

This procedure establishes standard requirements for corrective and preventive actions following quality events and confirmed out-of-specification results.

A CAPA must be raised and the investigation completed within 15 working days of an OOS result being confirmed.

Priya Rao, QA Lead, owns deviation management and oversees CAPA root cause analysis across manufacturing lines.

SOP-021 CAPA Management - Page 2

Section 2. Investigation and Closure:

All investigations require cross-functional review by Quality Assurance before closure.

Corrective actions must eliminate the verified root cause to prevent recurrence of deviations.