
CA-04 CORE & EJECTOR CONNECTOR WIRING DIAGRAM

M/C Side Core / Ejector Confirmation Connector



M/C Side Visible confirmation with Dummy on I/O Page



M/C Side Connector Wiring Detail

•	Core 1 SET	Pin = 1
•	Core 1 PULL	Pin = 2
•	Core 2 SET	Pin = 3
•	Core 2 PULL	Pin = 4
•	EJECTOR	Pin = 14 / 5
•	SMPS +ve 24volt	Pin = 13
•	SMPS -ve 24volt	Pin = 15/16