Prerequisites for verifiable scales

- Verifiable weighing cell with SENSE cables (6 leads), cell sensitivity 2 mV/V or 3 mV/V
- Scale configured as verifiable
- Labelling in accordance with regulations by the plant engineer, if the complete weighing system was not supplied by METTLER TOLEDO.

Assignment of the interface connections 4.2

	Digital I/O	RS232	RS422	RS485	USB Device	Ethernet	Power
Socket	11 5 6 7 12 4 0 0 0 8 3 0 0 0 9 2 10 1	5 4 0 0 6 3 0 8 0 7	3 2 0 0 0 6 0 5	3 2 0 0 0 6 0 5	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	3 0 0 4 2 0 1	4
Pin 1	In O	CTS	TxD+	T/RxD+	+5 V	TD+	+12 V
Pin 2	In 1	TxD	TxD-	T/RxD-	D-	RD+	+12 V
Pin 3	In 2	RTS	RxD+	_	GND	TD-	GND
Pin 4	In 3	RxD	+12 V	+12 V	D+	RD-	GND
Pin 5	In_GND	+12 V	GND	GND			
Pin 6	Out 0	+5 V	RxD-	_			
Pin 7	Out 1	_			•		
Pin 8	Out 2	GND					
Pin 9	Out 3		-				
Pin 10	Out_GND						
Pin 11	+12 V						
Pin 12	GND						