



Repair Order



No. : KA-ROI-1404-405

Date : 13/08/2025

Priority : Routine

Deadline : 13/09/2025

Company : TAMO

Item 1 Of 1

Component Information

RO No. : RO-1404-13681

A/C Type : MD80

Reg. : EP-LCL

Description : LIGHT ANTI COLL./POS./STROBE

ATA : 33

QTY : 1.00

Part Number : GE16720-010-2

TSO : UNK

TSN : UNK

Serial Number : AL842

CSO : 0

CSN : UNK

Reason Of Removal

POSITION LIGHT INOP

Work To Be Done

☐ Overhaul ☒ Repair ☒ Test ☐ Modification ☐ Other

Work Detailed To Be Performed

TEST AND REPAIR AS REQUIRED .

Packing Status

Box NR	Length	Width	Height	Weight

Issued By

Name : Mehdi Soltani

Sign. :

Approved By

Name :

Sign. :



Receiving Inspection Check List

Condition	Work Order No:	2508-03-01
☒ Unserviceable A/C Component	☐ Surplus / Used	☐ Others Pls. Specify:
☐ Consumable / Raw materials	☐ Unsalvageable	☐ Tools
Part Description		Customer Ref.
AFT ANTI-COLLISION / POSITION LIGHT		
P/N	S/N	QTY Invoice / RO Number
GE16720-010-2	AL842	1 RO-1404-13681

Item	Description	Satisfied	Unsatisfied	Remark
1	Check the LRU Part Number Existence in The "TAMO Capability List".	OK	-	CLN: C5-129
2	Check Packaging Condition IAW ATA-300	OK	-	
3	Check ESD Protection Condition of The Component IAW MOE Procedure.	OK	-	Has Protection Cap (Black Color)
4	Check Component General Condition for any Damage and Defect.	OK	-	
5	Checks the Packing List Against the Received Item and Purchase Order Request. (If Applicable)	N/A	-	
6	Check Component Documentation in Accordance with MOE Procedure.	OK N/A	✓	As customer's Report v/s tag isn't available to send.
7	Check Tools Documentation In Accordance with MOE Procedure.	-	-	
8	Check if any Extra Accessories Received with the Component. (Pls. Specify in Remark)	☐ Yes ☒ No	Remark: TAMO Warranty Seal Intact Yes ☐ No ☒	

Shipment Arrival Date:	16/Aug/2025	Inspection Date:	16/Aug/2025
------------------------	-------------	------------------	-------------

Final Decision
☒ Accept ☐ Reject Reason :

Receiving Inspection Performed By	
Name: M. Rahmati	Stamp/Sign:



Component Unserviceable Tag

Work Order No.: 2508-03-01

Customer Ref.: RO-1404-13681

DES: AFT ANTI-COLLISION / POS. LIGHT

P/N: GE16720-010-2

S/N.: AL842

A/C Type: MD80

A/C REG: EP-LCL

POS:

Reason for Removal:
POSITION LIGHT INOP

Store SUP
Stamp:



Date Removed:

Removed by:



Work Order

W/O No.: 2508-03-01

Customer Ref. No: RO-1404-13681

Priority

ROUTINE

Incoming Date: 17/Aug/2025

Form Issue Date: 17/Aug/2025

Issued By:

N. Panahi

Outgoing Date: 08, SEP, 2025

Production & Planning

Component Information

DES:	AFT ANTI-COLLISION / POS. LIGHT	A/C Type:	MD80	A/C REG:	EP-LCL
Part Number:	GE16720-010-2	TSO	-	ATA Chap.:	33
Serial Number:	AL842	Station:	-	Removal Date:	-

Reported Defect (Reason for Removal)

POSITION LIGHT INOP

Tasks Ordered

CMM/Ref.: 33-40-01	Test ☒	Repair ☒	Modify ☐	Overhaul ☐	Others ☐
Rev.:(8) Date: DEC/12/13	Specify in Remark				

Remark:

Work Carried Out

Tech.

SUP

1)Visual Inspection: OK ☒ Not OK ☐ Remark:

2)Initial Cleaning Performed: ☒

TAMO Warranty Seal Intact Yes ☐ No ☒

3)Functional Test Passed Yes ☐ No ☒

-Other Defects Confirmed:

4)Reported Defect Confirmed Yes ☒ No ☐

Tasks Performed:

5)Disassembly: ☒

Unit Disassembled As Task No.: 33-40-01-99F-810-A01

6)General Cleaning: ☒

General Cleaning Done Completely As Task No.: 33-40-01-99F-811-A01.

7)Repaired Tasks Performed: ☒

LAMP ASSEMBLY Replaced by New One Received from Customer). Unit Repaired As Task No.:33-40-01-99F-813-A01.

Repair Tasks(Cont.)

8)Defective Parts:☒

IPL Figure 1 Sheet 1 Item 5 Found Def.

9)Assembly:☒

Unit Assembled As Task No.: 33-40-01-99F-814-A01.

10)Fits and Clearances: ☐

N/A

Repair Tasks(Cont.)▶

11)Final Functional Test as CMM/Ref.: 33-40-01 Rev.:(8)Date: DEC/12/1 Passed ☒

Final Inspection and Release to service Control

Maintenance Data Control OK ☒ Maintenance Implementation Control OK ☒

Tools & Equipments Status Control OK ☒ Maintenance Record Control OK ☒

All Maintenance Task Requested by Customer Performed IAWCAA.IRI PART-145 Requirements Except Otherwise Specified in Remark.

Remark:

CC/S Stamp

WorkShop



Component Repair Report

(Part Used & Man-hours)

W/O No.: 2508-03-01

Customer Ref. No: RO-1404-13681
Issue Date: 17/Aug/2025

Priority ROUTINE
Issued By: N. Panahi

Incoming Date: 17/Aug/2025
Outgoing Date: 08/SEP/2025

Component Information

Description:	AFT ANTI-COLLISION / POS. LIGHT	A/C Type:	MD80	A/C REG:	EP-LCL
Part Number:	GE16720-010-2	TSO:	-	ATA Chapter:	33
Serial Number:	AL842	Station:		Removal Date:	-

Reason for removal

POSITION LIGHT INOP

Tasks Ordered

CMM Ref.: 33-40-01
Rev.: (8) Date: DEC/12/13

Test & Insp. ☒ Repair ☒ Overhaul ☐ Modify ☐ Others ☐
Specify in Remark

Remark:

Work Carried Out (Print or Capital Handwriting)

LAMP ASSEMBLY Replaced by New One (Received from Customer). Unit Repaired
As Task No.:33-40-01-99F-813-A01.

Part used

Description	Part No	QTY	S Price	Invoice No.	Remarks
LAMP ASSEMBLY	GE16731-2	1	\$200		

Man-hours

Date	Hours	Sign	Date	Hours	Sign
20/Aug/2025	8				

Total Hours: 8

CCS Hours	CCS Sign	Sup Hours	Sup Sign
1		1	

Production Control Remark:




A/C Component subassembly / Part Request

Request No: *RN0022*Request Date: *20/ Aug, 2025*NHA Part number:
*GE16720-010-2*NHA Description:
*AFT Anti-Collision / Pos. Light*Work Order No:
*2508-03-01*Customer Ref:
RD-1404-13681


Row	Part Number	Part Description	IPC Page	IPC FIG.	IPC Item	IPC Chapter	QTY	Remark
1	<i>GE16731-2</i>	<i>LAMP ASSEMBLY</i>	<i>10021</i>	<i>1</i>	<i>5</i>	<i>33-40-01</i>	<i>1</i>	
2								
3								
4								
5								
6								

Requested By:

Sign /Stamp:


m. Rahmeti

PC Supervisor Sign:


*L. Tanehi*Priority (Pls. ☒ Intended & ☐ Others)

Normal

☒

Top Urgent

Urgent

☐

AOG

Approved By:

Sign /Stamp:


Pourhossein

Customer Confirmation Required (Yes / No) :

Remark:

1.

PART OR MATERIAL CERTIFICATION FORM

ATA SPECIFICATION 106

2. Seller's Name:

3. Reference # 2263245

DASI

aircraft spares: in stock, online, on time

4. Organization: DASI LLC

Address: 10000 NW 25 St.
Doral, FL 33172

Phone #: 305-234-2333

Fax: 305-234-6100

SITA/Wire Code:

Status: Accredited Parts Distributor
FAA AC 00-56

5A. Seller's Contract #: 464734

5B. Buyer's Contract #: PO-000234

6. Item 7. Description

8. Manufacturer Part #

9. Eligibility

10. Qty 11. Serial/Batch # 12. Status

1. LIGHT ASSY

GE16731-2

MD

15

N/A

NEW

13A. Remarks

TO THE BEST OF OUR KNOWLEDGE, THIS PART HAS NOT BEEN SUBJECTED TO CONDITIONS OF EXTREME STRESS, HEAT OR ENVIRONMENT. THE PART WAS NOT PREVIOUSLY INSTALLED IN A PUBLIC AIRCRAFT, SUCH AS A GOVERNMENT USE AIRCRAFT OR A MILITARY AIRCRAFT.

Traceable To: GEMINI ENGINEERING

13B. Obtained From

GEMINI ENGINEERING/

VAS Aero Services

13C. Last Certificated Agency

GEMINI ENGINEERING

14. New Parts/Material Verification:

The following signature attests that the part(s) or material(s) identified above was (were) manufactured by a FAA Production Approval Holder (PAH), or to an industry or commercial standard.

15. Signature

16. Name

RAYMOND CARABAJALES

17. Date

1/13/2020

18. Used, Repaired or Overhauled Parts Verification:

The following signature attests that documentation specified above or attached is accurate with regard to the item(s) described.

19. Signature

20. Name

17. Date

1/13/2020



NOTICE: The above signature binds the seller and the SIGNER to the accuracy of the information provided in the form. Should the information provided in this FORM contain inaccuracies or misrepresentations, the signer and the SELLER may be liable for damages and be subject to criminal prosecution under state and federal law.




UTC Aerospace Systems


Goodrich Lighting Systems

COMPONENT MAINTENANCE MANUAL

GE16720-010-2, -2D, -6, 9 & -10



1B -6 ASSEMBLY CONFIGURATION



1A -2 ASSEMBLY CONFIGURATION

Light Assembly, AFT Anti Collision/ Position (GE16720-010-2, -6)

IPL Figure 1 Sheet 1 / GRAPHIC 33-40-01-99B-001-A01



UTC Aerospace Systems

COMPONENT MAINTENANCE MANUAL

GE16720-010-2, -2D, -6, 9 & -10


FIG.ITEM	PART NUMBER	AIRLINE STOCK NUMBER	NOMENCLATURE 1234567	EFFECT CODE	UNITS PER ASSY
1	-1	GE16720-010-1	LIGHT ASSEMBLY, AFT ANTI-COLLISION/ POSITION W/ FAULT INDICATOR OBSOLETE	A	RF
	-1A	GE16720-010-2	LIGHT ASSEMBLY, AFT A/C & POSITION, LEFT WING	B	RF
	-1B	GE16720-010-6	LIGHT ASSEMBLY, AFT A/C & POSITION, RIGHT WING	C	RF
	-1C	GE16720-010-10	LIGHT ASSEMBLY, AFT A/C & POSITION, RIGHT WING OBSOLETE	D	RF
	-2	GE16727-1	.LENS/BEZEL ASSEMBLY - (REV J) ORP (SEE IPL FIGURE 8 FOR BREAKDOWN)	A,B	1
	-2A	GE16727-2	.LENS/BEZEL ASSEMBLY - (REV J) ORP (SEE IPL FIGURE 8 FOR BREAKDOWN)	C	1
	2B	GEX0199-1	SCREW, CAPTIVE (MOVED TO ITEM 2G)		
	-2C	GE16494-1	GASKET, BEZEL (MOVED TO ITEM 2H) ORP		
	2E	018015-1	.LENS/BEZEL ASSEMBLY (FOR DETAILS SEE IPL FIGURE 8)	D	1
	-2F	205994	GASKET, BEZEL (MOVED TO ITEM 2J) (NP)		
	-2G	GEX0199-1	..SCREW, CAPTIVE	A, B, C	2
	2H	GE16494-1	..GASKET, BEZEL ORP	A, B, C	1
	2J	205994	..GASKET, BEZEL	D	1
	3	GE16885-1	.FLASH TUBE MODULE ASSEMBLY (FOR DETAILS SEE IPL FIGURE 9) ORP		1
	4	832X3-8FH	.SCREW, FLAT HEAD (CORRECT P/N 832X3/8FH)		4
	5	GE16731-2	.LAMP ASSEMBLY ORP		2

- ITEM NOT ILLUSTRATED

R = REVISION

ORP = OEM REPAIR PHILOSOPHY

OSO = ONLY SERVICEABLE BY OEM

1. Approving Competent Authority/Country  CAA.IRI		2. AUTHORIZED RELEASE CERTIFICATE CAA.IRI FORM 1			3. Form Tracking Number T0063	
4. Organization name and Address: Technical Arya Maintenance Organization No.101, Ofogh Building ,10 th, Eastern Alley,3 th Bimeh St, Ekbatan Town, Tehran 					5. Work Order/Contract/Invoice 2508-03-01	
6.Item	7. Description	8. Part No.	9. QTY	10. Serial No.	11. Status/Work	
1	AFT ANTI-COLLISION / POSITION LIGHT	GE16720-010-2	1	AL842	Repaired	
12. Remarks Unit Repaired, Inspected and Tested As CMM 33-40-01 Rev.(8) Dated: DEC/12/13, Found Ok.						
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation ☐ Non-approved design data specification in block 12			14a. ☒ Part-145. A.50 Release to Service ☐ Other regulation specified in block 1 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.			
13b. Authorized Signature		13c. Approval/Authorization Number		14b. Authorized Signature 		14c. Certificate/Approval Ref. No IR.145.99
13d. Name		13e. Date (dd mmm yyy)		14d. Name Alireza Arani Kashani 		14e. Date (dd mmm yyyy) 07/Sep/2025
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						